



Your Ref : SNM18D05019/C01/TOHHS

Date: 19th Nov 2021

Our Ref : CS/CTI21010620/Gty3e2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE GBH 2532C
ACCIDENT ON 20/10/2018**

Instruction was received to inspect the vehicle Reg. No. GBH 2532C. The inspection was conducted on 19/10/2021 at the premises of M/s 68 Kaki Bukit Avenue 6, #02-04/05, ARK@KB, Repairer: Jin Auto Services Pte Ltd.

The following vehicle information was recorded:

Registration Number : GBH 2532C
Make/Model : Toyota Hiace DX 3.0 Manual
Year of Registration : 2018
Body Colour : Silver
Chassis Number : KDH2010228569
Engine Capacity : 2982 cc

The vehicle sustained damages at the front portion, o/s, n/s body, undercarriage and rooftop. (Details see photographs enclosed)



In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 82,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 29,217.00
Nett Liability	<u>S\$ 52,783.00</u> =====

Vehicle Inspected By:

XING GUO QIANG
M.MATAI, AMSAE-A
Automotive Assessor

K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust),MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE,MIMI,MSAE,MCIARD, AM,NIJAAR(USA),
AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.