

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop n/y's Trans Cab

Insured: SKR 7558L

Policy No. MQ000821

Claims No. M2104793

Sum Insured: _____ Excess: _____
(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 40,750

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: S11D 78k Yr Regn: 08, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Renault Latitude C.C. 1995

Colour: M. White / Red A/C: Insured / Std / NI / NA

Sp. Reading: 371207 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VIFIABL15AUC 283326

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Sailun

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 7 mm

L/Bal. 8 mm L/Bal. 7 mm

D.O.A. 13/10/21 D.O.I. 14/10/2021

Survey held at _____

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

FR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-------------|--|
| | <u>CAA not ready, set video.</u> |
| 15/10/21 | <u>11 Rm @ 2250</u> Kenneth confirmed (Red 11,514.10, 83%) |

Date/Time, File Pass to? : Prell. Report
 : Final Report

1) _____
2) 18/10/21-typist

Days Of Repair: 2

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

| | |
|-----------------|--|
| Survey Fee: | |
| Transportation: | |
| S - RS: \$ | |
| Fuel: | |
| Others: | |
| TOTAL | |

Report Format: Merimen

Lump Sum / I.B.I: (\$ 2250)

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD78K

AAD2110-

*Not Authored
11 Sep & 2020*

Vehicle No.:
Chassis No.:
Vehicle Make: **14 OCT 2021**
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

SHD78K
VF1ABL15AUC283326
RENAULT
LATITUDE
13/10/2021
TOKIO
31/08/2016

| PART | LIST |
|-----------------------------|----------------------|
| 1 BUMPER COVER FRT | \$ Bu 747.20 ✓ |
| 1 BUMPER ABSORBER FRT | \$ In 394.68 X |
| 1 BUMPER BEAM FRT | \$ N 663.70 X |
| 1 BUMPER BRACKET KIT FRT RH | \$ Dri 101.40 ✓ |
| 1 HEADLAMP RH | \$ My car 743.60 ✓ |
| 1 WIPER RESERVOIR | \$ Bu 179.60 X |
| 1 FENDER PANEL FRT RH | \$ Bu 437.10 ✓ |
| 1 WHEELARCH FRT RH | \$ In 191.40 X |
| | \$ 3,267.28 |
| | 10% \$ 326.73 |
| | \$ 2,940.55 |

| Special Nett | |
|-------------------------------------|-------------------------------|
| 1SET BUMPER BRACKET CTR CLIP | \$ na na 33.00 X |
| 1SET BUMPER BRACKET SIDE CLIP RH RR | \$ na 10.00 X |
| 1SET BUMPER RETAINER RH CLIP RR | \$ na 20.00 X |
| 1SET BUMPER BRACKET SIDE CLIP LH RR | \$ na 10.00 X |
| 1SET BUMPER RETAINER CLIP LH RR | \$ na 20.00 X |
| 1 BUMPER CLIP FRT | \$ nke 85.00 65.00 |
| 1 FENDER CLIP | \$ in 65.00 X |
| 1 FENDER LINER CLIP | \$ na 60.00 X |
| TOTAL | \$ 303.00 |
| TOTAL PARTS | \$ 3,243.55 |

| LABOUR | |
|---|------------------------|
| Putty And Spray Painting Of The Affected Portion. | \$ 3,000.00 <i>440</i> |

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD78K

AAD2110-

| | | | |
|---|----|-----------|------|
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$ | 3,000.00 | 4000 |
| To Rust-Proofing Of The Affected Areas. | \$ | 170.00 | 300 |
| To reinstall rear bumper parking sensor. | \$ | na 170.00 | X |
| To transfer of bootlid fittings, attachments and perform water seepage test. | \$ | na 170.00 | X |
| To repair and realign rear exhaust pipe. | \$ | na 170.00 | X |
| To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe. | \$ | na 170.00 | X |
| To transfer of rear end panel fittings, attachment and perform water seepage test. | \$ | na 170.00 | X |
| To transfer of rear windscreen fittings and conduct water seepage test. | \$ | na 170.00 | X |
| To check steering geometry and computer wheel alignment | \$ | na 220.00 | X |
| To Check Electrical Lighting Concerned. | \$ | 170.00 | 200 |

TOTAL \$ 7,580.00

Over All Total \$ 13,764.10

**(LUMP SUM)
Repair Days**

**10 DAYS
2 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey - s on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: