

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21010625/UUY3N2**Date:** 26/10/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00015532100
<b>Claimant Vehicle No :</b>	SML6355U	<b>Insured Vehicle No :</b>	XE800Y
Date of Loss:	12/10/2021	Nature of Claim:	TP
		Claim No:	SNM21D205853/C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SML6355U</b>	Engine No:	L15B6002092
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Chassis No:	GK82001750
Reg. Date:	29/05/2019 (Man. Year: 2019)	Odometer:	42669 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,481.30	1,621.36	859.94	34.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,030.00	800.00	230.00	22.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>3,511.30</b>	<b>2,421.36</b>	<b>1,089.94</b>	<b>31.04</b>

**INSPECTION**

Date of Assignment:	15/10/2021	Unimotor Company - Kaki Bukit (HQ) 1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT) Singapore 417883
Date Inspected:	18/10/2021 Inspected At:	
Estimated Period of Repair:	2.0 days	

**Adjuster:** MARCUS CHUA**Manager:** Tan Hui Zhen

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 25 Oct 2021)	
<b>Parts:</b>	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SML6355U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS	Cracked	2,345.00 FL	*1,863.20 FL
2	1		*FRONT WINDSCREEN MOULDING	Necessary	312.00 FL	*88.50 FL
3	1		*FRONT WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
4	1		*FRONT ERP BRACKET	Necessary	30.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>2,747.00</b>	<b>2,011.70</b>
<b>- List Item Discount on L Items 10.00/20.00% (S\$)</b>	265.70	390.34
<b>Total Parts (S\$)</b>	<b>2,481.30</b>	<b>1,621.36</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PUTTY AND RESPRAY FRONT BUMPER/FRONT BONNET	New	600.00	500.00
2	TO RENEW FRONT WINDSCREEN V COOL STICKER	New	250.00	180.00
3	TO DISM/RENEW FRONT WINDSCREEN	New	180.00	120.00
<b>Gross Labour Cost (\$)</b>			<b>1,030.00</b>	<b>800.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >