

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010628/KTY3N2**Date:** 11/11/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00114052100

Claimant Vehicle No : SMC8443H**Insured Vehicle No :** SLJ3481E

Date of Loss: 13/10/2021

Nature of Claim: TP

Claim No: SNM21D205850/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMC8443H**

Make & Model: MITSUBISHI ATTRAGE, 1.2 (A)

Engine No: 3A92UGY0764

Reg. Date: 25/07/2018 (Man. Year: 2018)

Chassis No: MMBSTA13AJH002216

Colour: Metallic Silver

Odometer: 30675 km

Engine Capacity: 1193 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55R15

Rear Tyre Size:

185/55R15

Front Left Side: Yokohama 8 mm

Rear Left Side:

Yokohama 8 mm

Front Right Side: Yokohama 8 mm

Rear Right Side:

Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,480.00	3,347.00	2,133.00	38.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,750.00	2,360.00	1,390.00	37.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,230.00	5,707.00	3,523.00	38.17
Approved Total (Overridden) (S\$)		4,550.00		
(S\$)	9,230.00	4,550.00	4,680.00	50.70
+ GST 7.00/7.00% (S\$)	646.10	318.50	327.60	50.70
Nett Amount (S\$)	9,876.10	4,868.50	5,007.60	50.70

INSPECTION

Date of Assignment: 15/10/2021

Date Inspected: 15/10/2021

Inspected At:

Cartimes Autolution Pte Ltd
160 Sin Ming Drive #02-04 Autocity,
Singapore 575722

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Nov 2021)
Parts:	143	mitsubishi attrage 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC8443H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT	Bent	650.00 FL	*650.00 FL
2	1		*BOOT INNER TRIM	No such part	250.00 FL	*- FL
3	1		*BOOT LOCK ASSY	Repair	200.00 FL	*- FL
4	1		*BOOT HINGE LHS	Repair	190.00 FL	*- FL
5	1		*BOOT HINGE RHS	Repair	190.00 FL	*- FL
6	1		*ATTRAGE EMBLEM	Necessary	40.00 FL	*40.00 FL
7	1		*MITSUBISHI EMBLEM	Necessary	50.00 FL	*50.00 FL
8	1		*REAR BUMPER	Bent	660.00 FL	*660.00 FL
9	1		*REAR BUMPER RETAINER RHS	Cracked	30.00 FL	*30.00 FL
10	1		*REAR LOWER BUMPER	Buckled/Cracked	350.00 FL	*350.00 FL
11	1		*REAR LOWER BUMPER COVER	No such part	420.00 FL	*- FL
12	1		*END PANEL	Bent	410.00 FL	*410.00 FL
13	1		*END PANEL TOP GARNISH	Serviceable	80.00 FL	*- FL
14	1		*BOOT WEATHERSTRIP	Distorted/Dented	150.00 FL	*150.00 FL
15	1		*SPARE TYRE PANEL	Repair	990.00 FL	*- FL
16	1		*TAIL LAMP RHS	Cracked	280.00 FL	*280.00 FL
17	1		*TAIL LAMP PANEL RHS	Bent	80.00 FL	*80.00 FL
18	1		*REAR FENDER RHS	Buckled	730.00 FL	*730.00 FL
19	1		*REAR FENDER INNER SHIELD RHS	Serviceable	50.00 FL	*- FL
20	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*60.00 FS
21	1		*REAR SENSORS	Shorted	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,060.00	3,690.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	580.00	343.00
Total Parts (\$\$)	5,480.00	3,347.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;REPLACE DAMAGED PARTS AND COMPONENTS	New	1,600.00	1,200.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	1,800.00	1,000.00
3	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS	New	100.00	20.00
4	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	100.00	90.00
5	TRANSFER BOOT PARTS	New	150.00	50.00
Gross Labour Cost (\$)			3,750.00	2,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >