

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19960/198R GS1 Reg. No. 19-960/196-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref	CS/AGI21010629/Ktf3n2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date	e: 08/11/2021	
			Cod	le: AGI	
1.		Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SJW 7701A	Veh. Inspected	SLT 5674A	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10012069 /JM	Excess (\$)	0.00	
	Assign From	CHRISTINA	Assign Date	15/10/2021	
2.	2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI ELANTRA (A)	c.c	1591	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	KMHD841CMJU570014	Colour	WHITE	
	Odometer	72726 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	YOKOHAMA	8 mm	
	L/H Front Tyre	195/65 R15	YOKOHAMA	8 mm	
	R/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm	
	L/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.				
	DAMAGES SEE D	DAMAGES SEE DETAILS.			
5.	General Information				
	Accident Date	14/10/2021	Inspection Date	18/10/2021	
	Survey held at FALCON-AIR AUTO SERVICES PTE LTD (HQ)				
		176 SIN MING DRIVE #01-06/07/13, SIN MING AUTOCARE SINGAPORE 575721			
5a.		Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	FOTIMATED NORMAL DEDICE FOR DEDAIR				

**6 Working Days** 

ESTIMATED NORMAL PERIOD FOR REPAIR: