

AUTO PERFORMANCE APPRAISAL

APA

TAX INVOICE

Poh Ah Chye
C/O Chew Goon Motor
Blk 10 Ang Mo Kio Industrial Park 2A
#01-15, 16, 17 & #03-05 AMK AutoPoint
Singapore 568047

INVOICE NO : APA20002204

DATE : 21/05/2021

VEHICLE NO : SMH1689K

JOB REFERENCE NO : 20/002300

ACCIDENT DATE : 19/04/2021

SURVEY DATE : 21/04/2021

<u>DESCRIPTION</u>	<u>AMOUNT</u>
Survey Fees Inclusive Of Transportation Photographs	\$550.00
TOTAL AMOUNT	\$550.00

Notes :

All cheque payment should be "Crossed" and made payable to "Auto Performance Appraisal"

Auto Performance Appraisal



AUTO PERFORMANCE APPRAISAL

APA

VEHICLE SURVEY REPORTS																																				
Poh Ah Chye C/O Chew Goon Motor Blk 10 Ang Mo Kio Industrial Park 2A #01-15, 16, 17 & #03-05 AMK AutoPoint Singapore 568047																																				
1	Reference Job Reference No : 20/002300 Claim No : - Claim Type : Third Party Accident Date : 19/04/2021 Survey Date : 21/04/2021 Survey Report Date : 21/05/2021																																			
2	Particulars Of Vehicle Vehicle Registration No : SMH1689K Make & Model : Honda Shuttle Hybrid 1.5 Vehicle Registration Date : 12/06/2018 Chassis No : GP71213382 Engine No : Blocked Colour : Silver																																			
3	Condition Of Vehicle And Tyres <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left;"><u>Mileage (KM)</u></th> <th style="text-align: left;"><u>Brakes</u></th> <th style="text-align: left;"><u>Steering</u></th> <th style="text-align: left;"><u>Modification</u></th> </tr> </thead> <tbody> <tr> <td>181933</td> <td>Serviceable</td> <td>Serviceable</td> <td>None</td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <th style="text-align: left;"><u>Tyres</u></th> <th style="text-align: left;"><u>Make</u></th> <th style="text-align: left;"><u>Size</u></th> <th style="text-align: left;"><u>Balance (MM)</u></th> </tr> <tr> <td>Front RHS</td> <td>Maxxis</td> <td>195/55R15</td> <td>5</td> </tr> <tr> <td>Front LHS</td> <td>Maxxis</td> <td>195/55R15</td> <td>5</td> </tr> <tr> <td>Rear RHS</td> <td>Maxxis</td> <td>195/55R15</td> <td>6</td> </tr> <tr> <td>Rear LHS</td> <td>Maxxis</td> <td>195/55R15</td> <td>6</td> </tr> </tbody> </table>				<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>	181933	Serviceable	Serviceable	None					<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>	Front RHS	Maxxis	195/55R15	5	Front LHS	Maxxis	195/55R15	5	Rear RHS	Maxxis	195/55R15	6	Rear LHS	Maxxis	195/55R15	6
<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>																																	
181933	Serviceable	Serviceable	None																																	
<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>																																	
Front RHS	Maxxis	195/55R15	5																																	
Front LHS	Maxxis	195/55R15	5																																	
Rear RHS	Maxxis	195/55R15	6																																	
Rear LHS	Maxxis	195/55R15	6																																	
4	Description Of Damages The vehicle sustained damages at frontal & rear right hand side portion. (For information of damages please refer to Parts/Labour/Photographs attached)																																			
5	Instruction This survey was conducted entirely on a "WITHOUT PREJUDICE" basis, and we have not authorised any repair.																																			

AUTO PERFORMANCE APPRAISAL

Annex A

Vehicle Assessment Reports

Ref No : 20/002300

Damage And Repair Cost Adjustment

<u>S/No</u>	<u>Qty</u>	<u>Parts Description</u>	<u>Comments/condition</u>	<u>Workshop Estimate (\$)</u>	<u>Our Assessment (\$)</u>
<u>List Items</u>					
1	1	Bonnet	Dented	1,012.00	1,012.00
2	1	Bonnet Rubber Seal	Serviceable/reuse	45.00	-
3	5	Bonnet Insulation Clips	Broken/necessary	25.00	25.00
4	1	Grille	Broken	426.00	426.00
5	1	Grille Emblem	Cut/necessary	32.00	32.00
6	14	Grille Chrome	Cut/grazed	390.00	390.00
7	1	Grille Lower Chrome Moulding	Cut/grazed	240.00	240.00
8	1	Grille Brace Bracket	Bent	85.00	85.00
9	1	Front Bumper	Deformed/dented	1,150.00	1,150.00
10	12	Front Bumper Clips	Broken/necessary	66.00	66.00
11	2	Front Bumper Brackets	Bent/necessary	84.00	84.00
12	1	Front Bumper Reinforcement	Buckled	327.00	327.00
13	1	Front Bumper Center Air Grille	Serviceable/reuse	155.00	-
14	2	Front Bumper Top Retainers	Deformed/necessary	34.00	34.00
15	1	Front Bumper Tow Cover	Deformed/broken	45.00	45.00
16	2	Front Bumper Corner Retainers	Broken/necessary	33.40	33.40
17	2	Headlamps	Broken/cracked	4,500.80	4,500.80
18	2	Headlamp Brackets	Deformed/broken	130.00	130.00
19	1	Support Panel	Dented/bent	846.00	846.00
20	1	Air Con Condenser	Bent	1,082.00	1,082.00
21	2	Air Con Condenser Side Air Ducts	Deformed/broken	110.00	110.00
22	1	Radiator	Dented	1,475.00	1,475.00
23	1	Air Cleaner Cold Air Intake Duct	Deformed/broken	225.00	225.00
24	1	Rear Bumper	Broken	1,150.20	1,150.20
25	8	Rear Bumper Clips	Necessary	44.00	44.00
				13,712.40	13,512.40
Less discount 20%				2,742.48	2,702.48
Total :				10,969.92	10,809.92
<u>Special Nett Items</u>					
26	1	Front Number Plate (Chrome 3D)	Bent/dented	120.00	120.00
27	1	Front Number Plate Holder	Bent/dented	80.00	80.00
				200.00	200.00
Total Spare Parts :				11,169.92	11,009.92

AUTO PERFORMANCE APPRAISAL

Vehicle Assessment Reports

Annex B

Ref No : 20/002300

Damage And Repair Cost Adjustment

<u>Items</u>	<u>Job Description</u>	<u>Workshop Estimate (\$)</u>	<u>Adjusted Costs (\$)</u>
1	To Conduct Electrical Check, Focus Headlamp.	30.00	20.00
2	To Remove / Refit Air Con Condenser & Refill Air Con Gas.	120.00	100.00
3	To Remove / Refit, Radiator System, Bleed, Refill Coolant.	60.00	30.00
4	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel.	60.00	60.00
5	Labour Charge - Panel Beating, Repairing Of Front Chassis Member, Inner Panel, Front Fender X2 Cnt, Weld Support & Parts Replacement.	1,100.00	800.00
6	To Spray Painting Affected Areas.	1,250.00	1,000.00
Total Labour :		<u>2,620.00</u>	<u>2,010.00</u>
Total Spare Parts :		11,169.92	11,009.92
Total Labour :		2,620.00	2,010.00
Total Repair Costs :		<u>13,789.92</u>	<u>13,019.92</u>

Assessor's Recommendation

Repairer Estimate : 13,789.92
 Our Adjustment : 13,019.92

Remarks

The repairer has agreed to undertake the repair of \$13,019.92, with a repair period of 8 working days.

Surveyed By:

Lek Boon Hwee
 Automobile Appraiser

AUTO PERFORMANCE APPRAISAL

Vehicle Assessment Reports

Annex B

Ref No : 20/002300

Damage And Repair Cost Adjustment

<u>Items</u>	<u>Job Description</u>	<u>Workshop Estimate (\$)</u>	<u>Adjusted Costs (\$)</u>
1	To Conduct Electrical Check, Focus Headlamp.	30.00	20.00
2	To Remove / Refit Air Con Condenser & Refill Air Con Gas.	120.00	100.00
3	To Remove / Refit, Radiator System, Bleed, Refill Coolant.	60.00	30.00
4	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel.	60.00	60.00
5	Labour Charge - Panel Beating, Repairing Of Front Chassis Member, Inner Panel, Front Fender X2 Cnt, Weld Support & Parts Replacement.	1,100.00	800.00
6	To Spray Painting Affected Areas.	1,250.00	1,000.00
Total Labour :		<u>2,620.00</u>	<u>2,010.00</u>
Total Spare Parts :		11,169.92	11,009.92
Total Labour :		2,620.00	2,010.00
Total Repair Costs :		<u>13,789.92</u>	<u>13,019.92</u>

Assessor's Recommendation

Repairer Estimate : 13,789.92
 Our Adjustment : 13,019.92

Remarks

The repairer has agreed to undertake the repair of \$13,019.92, with a repair period of 8 working days.


Surveyed By:



Lek Boon Hwee
Automobile Appraiser


APA

Job Reference No : 21/002300





APA

Job Reference No : 21/002300




APA

Job Reference No : 21/002300




APA

Job Reference No : 21/002300





APA

Job Reference No : 21/002300






APA

Job Reference No : 21/002300






APA

Job Reference No : 21/002300





APA

Job Reference No : 21/002300






APA

Job Reference No : 21/002300




APA

Job Reference No : 21/002300




APA

Job Reference No : 21/002300




APA

Job Reference No : 21/002300




APA

Job Reference No : 21/002300



APA

Job Reference No : 21/002300




APA



Job Reference No : 21/002300


APA

Job Reference No : 21/002300






APA

Job Reference No : 21/002300



APA

Job Reference No : 21/002300



APA

Job Reference No : 21/002300

