

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21010639/UEA3Q2**Date:** 15/08/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : PC9145B **Insured Vehicle No :** SNB9046H
 Date of Loss: 28/09/2021 Nature of Claim: TP Claim No: MFL2021D0004232

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PC9145B**
 Make & Model: TOYOTA HIACE, 2.8 D COMMUTER GL (A) Engine No: 1GD8455405
 Reg. Date: 13/02/2020 (Man. Year: 2019) Chassis No: GDH2232002326
 Colour: Silver Odometer: 31520 km
 Engine Capacity: 2754 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	622.20	310.55	311.65	50.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	380.00	200.00	180.00	47.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,002.20	510.55	491.65	49.06
+ GST 7.00/7.00% (S\$)	70.15	35.74	34.41	49.05
Nett Amount (S\$)	1,072.35	546.29	526.06	49.06
+ Loss of Use (2.0 x S\$140.00/day) (S\$)		280.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		833.74		

INSPECTION

Date of Assignment: 15/10/2021
 Date Inspected: 18/10/2021 Inspected At: Kt Garage Pte Ltd (HQ)
 BLK 1 KAKI BUKIT AVENUE 6 #01-04, AUTO
 BAY@KAKI BUKIT ENTRANCE A
 Singapore 417883
 Estimated Period of Repair: 1.0 days

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 May 2022)
Parts:	213	TOYOTA HIACE 2.8 D COMMUTER GL (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC9145B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Grazed	387.40 FL	*387.40 FL
2	8		*FRT BUMPER CLIP	Necessary	33.00 FS	*20.00 FS
3	1		*SIDE RETAINER LH	Not Necessary	128.70 FL	*- FL
4	1		*FRT FOG LAMP LH	Serviceable	269.50 FL	*- FL
					Sub Total (\$\$)	818.60 407.40
					- List Item Discount on L Items 25.00/25.00% (\$\$)	196.40 96.85
					Total Parts (\$\$)	622.20 310.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK AND STRAIGHTEN DAMAGE PANEL ,CUT & WELD NECESSARY PORTION AND REALIGN THE SAME	New	300.00	180.00
2	TO CHECK ALL LIGHTING AND WIRING	New	80.00	20.00
Gross Labour Cost (\$)			380.00	200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >