

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT | | | | | | |
|------------------------------|---|---|------------------|------------|-------------------------|--|
| | SOMPO INSURANCE SINGAPORE PL | | F | Ref: | CS3/SMO21010641/Kvf3e2 | |
| | 50 RAFFLES PLAC TOWER SINGAPO |] | Date: | 28/10/2021 | | |
| | | | (| Code: | SMO | |
| 1. | Policy Particulars :- (THIRD PARTY CLAIM) | | | | | |
| | Insured Veh. | GBF 5806D | Veh. Inspected | | FBP 7839T | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | CMTD2103065/THE | Excess (\$) | | 0.00 | |
| | Assign From | GRACE TEO | Assign Date | | 15/10/2021 | |
| 2. | Vehicle Particulars & Condition | | | | | |
| | Make & Model | YAMAHA X-MAX (A) | c.c | | 395 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2019 | |
| | Chassis No. | VG5SH121000010638 | Colour | | METALLIC BLACK | |
| | Odometer | 54408 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | STANDARD ALLOY RIM | |
| | General | GOOD | | | | |
| 3. | Conditions of Tyres | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 120/70 R15 | PIRELLI | | 3 mm | |
| | L/H Front Tyre | | | | mm | |
| | R/H Rear Tyre | 150/70 R13 | PIRELLI | | 4 mm | |
| | L/H Rear Tyre | | | | mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE N/S AND O/S BODY. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 09/10/2021 | Inspect Date / T | ime | 20/10/2021 (11:47 AM) | |
| | Survey held at | KENG HOCK MOTOR | | | | |
| | | 188 YIO CHU KANG ROAD, SINGAPORE 545635 | | | | |
| 5a. | | Remarks | | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000 | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days | | | | | |

Report Ref No. CS3/SMO21010641/Kvf3e2

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser