

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/GRB21010642/BES3Q2**Date:** 07/02/2022REFERENCE

|                              |                                       |                             |                 |
|------------------------------|---------------------------------------|-----------------------------|-----------------|
| Handling Insurer:            | India International Insurance Pte Ltd | Policy No:                  | D21MFL0000447   |
| <b>Claimant Vehicle No :</b> | SJU7741U                              | <b>Insured Vehicle No :</b> | SLM7858K        |
| Date of Loss:                | 15/10/2021                            | Nature of Claim:            | TP              |
|                              |                                       | Claim No:                   | MFL2021D0004539 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SJU7741U</b>                   | Engine No:  | 3ZZ4956919        |
| Make & Model:               | TOYOTA COROLLA ALTIS, 1.6 CVT (A) | Chassis No: | MR053ZEE106162788 |
| Reg. Date:                  | 28/12/2009 (Man. Year: 2009)      | Odometer:   | 213342 km         |
| Colour:                     | Silver                            |             |                   |
| Engine Capacity:            | 1598 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 195/65 R15   | Rear Tyre Size:  | 195/65 R15   |
| Front Left Side:  | Firenza 5 mm | Rear Left Side:  | Firenza 5 mm |
| Front Right Side: | Firenza 5 mm | Rear Right Side: | Firenza 5 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                           | 9,508.16          | 3,962.01          | 5,546.15          | 58.33         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour                                          | 4,080.00          | 1,740.00          | 2,340.00          | 57.35         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing                                          | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>13,588.16</b>  | <b>5,702.01</b>   | <b>7,886.15</b>   | <b>58.04</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>4,550.00</b>   |                   |               |
| <b>(S\$)</b>                                    | 13,588.16         | 4,550.00          | 9,038.16          | 66.51         |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 951.17            | 318.50            | 632.67            | 66.51         |
| <b>Nett Amount (S\$)</b>                        | <b>14,539.33</b>  | <b>4,868.50</b>   | <b>9,670.83</b>   | <b>66.51</b>  |
| <b>+ Car Rental (9.0 x S\$100.00/day) (S\$)</b> |                   | 900.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 7.45              |                   |               |
| <b>+ Other Costs (S\$)</b>                      |                   | 120.00            |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>5,895.95</b>   |                   |               |

INSPECTION

|                             |                          |                                                                                                           |
|-----------------------------|--------------------------|-----------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 15/10/2021               |                                                                                                           |
| Date Inspected:             | 18/10/2021 Inspected At: | Bifrost Auto Pte Ltd (Kaki Bukit)<br>8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit<br>Singapore 415875 |
| Estimated Period of Repair: | 7.0 days                 |                                                                                                           |

**Adjuster:** Lim Teow Guan**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 01 Dec 2021)

**Parts:** 143      TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SJU7741U)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

| No. | Qty | Part No. | Particulars                            | Condition     | Repairer's | Amount     |
|-----|-----|----------|----------------------------------------|---------------|------------|------------|
| 1   | 1   |          | *BOOTLID                               | Bent          | 909.70 FL  | *745.70 FL |
| 2   | 1   |          | *BOOTLID 1.6 EMBLEM                    | Necessary     | 28.10 FL   | *28.10 FL  |
| 3   | 1   |          | *BOOTLID CENTRE EMBLEM                 | Necessary     | 45.67 FL   | *45.67 FL  |
| 4   | 1   |          | *BOOTLID COROLLA EMBLEM                | Necessary     | 61.60 FL   | *46.60 FL  |
| 5   | 1   |          | *BOOTLID ALTIS EMBLEM                  | Necessary     | 49.85 FL   | *49.85 FL  |
| 6   | 1   |          | *BOOTLID LX EMBLEM                     | Necessary     | 36.50 FL   | *36.50 FL  |
| 7   | 1   |          | *BOOTLID CHROME MOULDING               | Not Damaged   | 234.60 FL  | *- FL      |
| 8   | 1   |          | *BOOTLID RH LAMP                       | Broken        | 228.90 FL  | *228.90 FL |
| 9   | 1   |          | *BOOTLID RH LAMP SPONGE GASKET         | Necessary     | 21.30 FL   | *21.30 FL  |
| 10  | 1   |          | *BOOTLID LH LAMP                       | Broken        | 228.90 FL  | *228.90 FL |
| 11  | 1   |          | *BOOTLID LH LAMP SPONGE GASKET         | Necessary     | 21.30 FL   | *21.30 FL  |
| 12  | 1   |          | *BOOTLID LOCK                          | Jammed        | 126.80 FL  | *126.80 FL |
| 13  | 1   |          | *BOOTLID LOCK CATCH                    | Not Damaged   | 45.70 FL   | *- FL      |
| 14  | 1   |          | *BOOTLID RH HINGE                      | Not Damaged   | 148.50 FL  | *- FL      |
| 15  | 1   |          | *BOOTLID LH HINGE                      | Not Damaged   | 148.50 FL  | *- FL      |
| 16  | 1   |          | *BOOTLID WEATHERSTRIP                  | Distorted     | 194.70 FL  | *194.70 FL |
| 17  | 1   |          | *BOOTLID INNER TRIM                    | Torn          | 251.60 FL  | *174.10 FL |
| 18  | 1   |          | *REAR BUMPER                           | Broken        | 523.90 FL  | *482.30 FL |
| 19  | 1   |          | *REAR BUMPER RH REFLECTOR              | Not Damaged   | 55.70 FL   | *- FL      |
| 20  | 1   |          | *REAR BUMPER LH REFLECTOR              | Not Damaged   | 55.70 FL   | *- FL      |
| 21  | 1   |          | *REAR BUMPER RH SIDE RETAINER          | Necessary     | 57.80 FL   | *35.00 FL  |
| 22  | 1   |          | *REAR BUMPER LH SIDE RETAINER          | Necessary     | 57.80 FL   | *35.00 FL  |
| 23  | 1   |          | *REAR BUMPER RH SIDE HOLDER BRACKET    | Dented        | 46.95 FL   | *46.95 FL  |
| 24  | 1   |          | *REAR BUMPER LH SIDE HOLDER BRACKET    | Dented        | 46.95 FL   | *46.95 FL  |
| 25  | 1   |          | *REAR BUMPER SPONGE WITH REINFORCEMENT | Broken        | 175.90 FL  | *175.90 FL |
| 26  | 1   |          | *REAR BUMPER RH IMPACT BRACKET         | Dented        | 97.90 FL   | *85.60 FL  |
| 27  | 1   |          | *REAR BUMPER LH IMPACT BRACKET         | Dented        | 97.90 FL   | *85.60 FL  |
| 28  | 1   |          | *RH TAILLAMP                           | Broken        | 438.00 FL  | *362.00 FL |
| 29  | 1   |          | *RH TAILLAMP SPONGE GASKET             | Necessary     | 22.50 FL   | *22.50 FL  |
| 30  | 1   |          | *SET RH TAILLAMP LOCK CLIPS            | Necessary     | 12.00 FL   | *12.00 FL  |
| 31  | 1   |          | *RH TAILLAMP LOWER BRACKET             | Broken        | 45.70 FL   | *45.70 FL  |
| 32  | 1   |          | *LH TAILLAMP                           | Broken        | 438.00 FL  | *362.00 FL |
| 33  | 1   |          | *LH TAILLAMP SPONGE GASKET             | Necessary     | 22.50 FL   | *22.50 FL  |
| 34  | 1   |          | *SET LH TAILLAMP LOCK CLIPS            | Necessary     | 12.00 FL   | *12.00 FL  |
| 35  | 1   |          | *LH TAILLAMP LOWER BRACKET             | Broken        | 45.70 FL   | *45.70 FL  |
| 36  | 1   |          | *END PANEL                             | Dented        | 590.60 FL  | *590.60 FL |
| 37  | 1   |          | *END PANEL INNER GARNISH               | Broken        | 202.70 FL  | *202.70 FL |
| 38  | 1   |          | *REAR WINDSCREEN GLASS RUBBER MOULDING | Not Necessary | 138.60 FL  | *- FL      |
| 39  | 1   |          | *REAR RH FENDER                        | Not Damaged   | 945.00 FL  | *- FL      |
| 40  | 1   |          | *REAR RH FENDER INNER TRIM             | Not Damaged   | 381.80 FL  | *- FL      |
| 41  | 1   |          | *REAR LH FENDER                        | Not Damaged   | 945.00 FL  | *- FL      |
| 42  | 1   |          | *REAR LH FENDER INNER TRIM             | Not Damaged   | 381.80 FL  | *- FL      |
| 43  | 1   |          | *SPARE TYRE PANEL                      | Repair        | 817.10 FL  | *- FL      |
| 44  | 1   |          | *SPARE TYRE PANEL COVER BOARD          | Broken        | 389.40 FL  | *276.60 FL |
| 45  | 1   |          | *EXHAUST SILENCER                      | Not Damaged   | 718.90 FL  | *- FL      |
| 46  | 1   |          | *EXHAUST SILENCER GASKET               | Not Damaged   | 38.20 FL   | *- FL      |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                          | Condition     | Repairer's | Amount     |
|-----|-----|----------|--------------------------------------|---------------|------------|------------|
| 47  | 1   |          | *SET REAR BUMPER CLIPS               | Necessary     | 70.00 FS   | *30.00 FS  |
| 48  | 1   |          | *SET REAR BUMPER REVERSE SENSOR      | Scratched     | 280.00 FS  | *200.00 FS |
| 49  | 1   |          | *REAR WINDSCREEN GLASS SEALANT       | Not Necessary | 70.00 FS   | *- FS      |
| 50  | 1   |          | *REAR WINDSCREEN GLASS INNER SEAL    | Not Necessary | 50.00 FS   | *- FS      |
| 51  | 1   |          | *REAR RH FENDER JOINT SEALANT        | Not Necessary | 70.00 FS   | *- FS      |
| 52  | 1   |          | *SET REAR RH FENDER INNER TRIM CLIPS | Not Necessary | 70.00 FS   | *- FS      |
| 53  | 1   |          | *REAR LH FENDER JOINT SEALANT        | Not Necessary | 70.00 FS   | *- FS      |
| 54  | 1   |          | *SET REAR LH FENDER INNER TRIM CLIPS | Not Necessary | 70.00 FS   | *- FS      |
| 55  | 1   |          | *END PANEL JOINT SEALANT             | Necessary     | 60.00 FS   | *30.00 FS  |
| 56  | 1   |          | *SET END PANEL INNER GARNISH CLIPS   | Necessary     | 50.00 FS   | *30.00 FS  |
| 57  | 1   |          | *BOOTLID REVERSE CAMERA              | Not Necessary | 550.00 FS  | *- FS      |
| 58  | 1   |          | *SET ROOF LINING CLIPS               | Not Necessary | 90.00 FS   | *- FS      |
| 59  | 1   |          | *SPARE TYRE PANEL JOINT SEALANT      | Not Necessary | 70.00 FS   | *- FS      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                    |           |          |
|----------------------------------------------------|-----------|----------|
| Sub Total (S\$)                                    | 12,154.22 | 5,186.02 |
| - List Item Discount on L Items 25.00/25.00% (S\$) | 2,646.06  | 1,224.01 |
| Total Parts (S\$)                                  | 9,508.16  | 3,962.01 |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                            | Particulars                                                                                                                        | Lab.Type | Repairer's      | Amount          |
|-------------------------------|------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>           |                                                                                                                                    |          |                 |                 |
| 1                             | LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS TO PANEL BEATING CUT/WELD AND REALIGN ALL AFFECTED PANELS | New      | 1,800.00        | 800.00          |
| 2                             | SPRAY PAINTING ON AFFECTED PANELS                                                                                                  | New      | 1,400.00        | 800.00          |
| 3                             | CHECK WIRING AND LIGHTING SYSTEM                                                                                                   | New      | 80.00           | 0.00            |
| 4                             | APPLY RUST COATING CHEMICAL ON AFFECTED PANELS                                                                                     | New      | 100.00          | 0.00            |
| 5                             | REMOVE AND REPLACE BOOTLID REVERSE CAMERA TO ASSIST REPAIR                                                                         | New      | 100.00          | 0.00            |
| 6                             | REMOVE AND REPLACE BOOTLID INNER COMPONENTS TO NEW BOOTLID                                                                         | New      | 100.00          | 80.00           |
| 7                             | REMOVE AND REPLACE REAR INNER TRIMS ,GARNISH ,ROOF LINING ,SEATS AND BOARDS TO ASSIST REPAIR                                       | New      | 280.00          | 0.00            |
| 8                             | REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR                                                                    | New      | 100.00          | 60.00           |
| 9                             | REMOVE AND REPLACE EXHAUST SILENCER AND RUBBER MOULDINGS TO ASSIST REPAIR                                                          | New      | 120.00          | 0.00            |
| <b>Gross Labour Cost (\$)</b> |                                                                                                                                    |          | <b>4,080.00</b> | <b>1,740.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >