

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21010644/BPA3Q2**Date:** 17/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210104748
Claimant Vehicle No :	JRL7883	Insured Vehicle No :	SDP2428E
Date of Loss:	01/10/2021	Nature of Claim:	TP
		Claim No:	2824888180SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	JRL7883	Engine No:	M401E037037
Make & Model:	YAMAHA MT-07, 689cc	Chassis No:	PMYRM1010F0037037
Reg. Date:	05/04/2016 (Man. Year: 2015)	Odometer:	0 km
Colour:	Black		
Engine Capacity:	689 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70 /17	Rear Tyre Size:	180/55/17
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,446.26	3,923.96	7,522.30	65.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,320.00	750.00	570.00	43.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,766.26	4,673.96	8,092.30	63.39
Approved Total (Overridden) (S\$)		3,750.00		
(S\$)	12,766.26	3,750.00	9,016.26	70.63
+ GST 7.00/7.00% (S\$)	893.64	262.50	631.14	70.63
Nett Amount (S\$)	13,659.90	4,012.50	9,647.40	70.63
+ Loss of Use (4.0 x S\$30.00/day) (S\$)		120.00		
+ Doc/Search Fee (S\$)		29.00		
+ Other Costs (S\$)		60.00		
Nett Liability (S\$)		4,221.50		
Global Sum Settlement (S\$)		4,200.00		

INSPECTION

Date of Assignment:	15/10/2021	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT Singapore 415875
Date Inspected:	18/10/2021 Inspected At:	
Estimated Period of Repair:	3.0 days	

Adjuster: Lim Teow Guan

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent	375.00 FL	*95.00 FL
2	1		*SET SWRHANDLE GRIP	Not Damaged	225.00 FL	*- FL
3	1		*CLUTCH LEVER	Cut	135.20 FL	*90.00 FL
4	1		*BEAKE LEVER	Cut	77.30 FL	*77.30 FL
5	1		*FRONT COWING	Cut	67.40 FL	*67.40 FL
6	1		*INNER TUBE COMP LH	Bent	286.60 FL	*286.60 FL
7	1		*SET FRONT MIRROR ASSY	Broken	162.50 FL	*162.50 FL
8	2		*SIDE FARTING R/L	Cut	515.60 FL	*342.00 FL
9	1		*SET FRONT BALANCER	Broken	136.50 FL	*60.00 FL
10	1		*FRONT FENDER	Cut	215.00 FL	*215.00 FL
11	1		*SET FORK ASSY	Bent	1,355.90 FL	*680.00 FL
12	2		*FORK STEM	Necessary	390.00 FL	*390.00 FL
13	1		*FRONT COWING	Repeated	146.00 FL	*- FL
14	1		*FRONT PILOT LIGHT	Not Damaged	163.20 FL	*- FL
15	1		*HEAD COVER	Cut	83.40 FL	*83.40 FL
16	1		*SET BEARING	Not Necessary	124.20 FL	*- FL
17	1		*GASKET PIPE	Not Damaged	64.50 FL	*- FL
18	1		*FRONT CALIPER ASSY	Not Damaged	74.80 FL	*- FL
19	1		*SEAT (GID)	Cracked	56.40 FL	*56.40 FL
20	2		*FRONT SIGNAL R/L	Not Damaged	292.80 FL	*- FL
21	1		*FRONT WHEEL SHAFT	Not Damaged	115.00 FL	*- FL
22	1		*FRONT BRAKE DISC	Not Damaged	225.00 FL	*- FL
23	1		*FRONT BRAKE CALIPER	Not Damaged	355.00 FL	*- FL
24	1		*FRONT BRAKE CABLE	Not Damaged	95.00 FL	*- FL
25	1		*SET SLIDER	Broken	273.40 FL	*160.00 FL
26	1		*RADIATOR	Not Damaged	445.30 FL	*- FL
27	2		*FOOT BRAKE R/L	Not Damaged	190.00 FL	*- FL
28	2		*FOOT REST ASSY RL	Not Damaged	570.00 FL	*- FL
29	1		*ENGINE TIMING OUTER COVER CASING	Not Damaged	255.00 FL	*- FL
30	1		*GEARBOX COVER OUTER CASING	Not Damaged	355.00 FL	*- FL
31	2		*FRONT SIGNAL RL	Repeated	295.00 FL	*- FL
32	1		*TAIL END GARNISH	Cut	275.00 FL	*275.00 FL
33	2		*REAR SIGNAL R/L	Missing	274.60 FL	*160.00 FL
34	1		*HEADLAMP	Cut	635.70 FL	*320.00 FL
35	1		*HEADLAMP COVER	Not Damaged	127.80 FL	*- FL
36	1		*HEADLAMP BRACKET	Necessary	147.60 FL	*147.60 FL
37	1		*LAMP STAY	Necessary	136.20 FL	*136.20 FL
38	1		*EXHAUST ASSY	Not Damaged	738.50 FL	*- FL
39	1		*SWING ARM	Not Damaged	625.00 FL	*- FL
40	1		*REAR NUMBER PLATE	Necessary	35.00 FS	*20.00 FS
41	1		*FORK OIL	Necessary	50.00 FS	*30.00 FS
42	1		*BRAKE FLUID	Not Necessary	50.00 FS	*- FS
43	1		*FRONT TYRE	Not Damaged	350.00 FS	*- FS
44	1		*TAIL BOX	Cut	450.00 FS	*450.00 FS
45	1		*HELMET	Not Necessary	380.00 FS	*- FS
46	1		*TAIL BOX BRACKET	Not Damaged	158.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,554.40	4,304.40
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,108.14	380.44
Total Parts (\$\$)	11,446.26	3,923.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WORKMANSHIP (EXHAUST RIM ,TYRE ,FORK BRAKE ,SWING ARM ,TAIL END ETC)	New	600.00	400.00
2	ELECTRICAL	New	80.00	20.00
3	TO CONDUCT CHASSIS ALIGNMENT	New	140.00	30.00
4	SPRAY PAINTING	New	500.00	300.00
Gross Labour Cost (\$\$)			1,320.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >