

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI21010658/VQF3N2**Date:** 03/11/2021REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MU012442		
Claimant Vehicle No :	SHD4297T	Insured Vehicle No :	SLU8431J		
Date of Loss:	15/10/2021	Nature of Claim:	TP	Claim No:	M2104799

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD4297T	Engine No:	G4LEKU401188
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVLU187788
Reg. Date:	30/10/2019 (Man. Year: 2019)	Odometer:	189780 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,639.28	786.88	2,852.40	78.38
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,420.00	1,930.00	490.00	20.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,070.28	2,727.88	3,342.40	55.06
+ GST 7.00/7.00% (S\$)	424.91	190.95	233.96	55.06
Nett Amount (S\$)	6,495.19	2,918.83	3,576.36	55.06

INSPECTION

Date of Assignment:	18/10/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	18/10/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	4.0 days		

Adjuster: Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Nov 2021)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD4297T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR DOOR ASSY RH	Repair	1,797.20 FL	-	*- FL
2	1		*REAR FENDER RH	Repair	1,768.30 FL	-	*- FL
3	1		*REAR BUMPER ASSY	Dented	459.40 FL	-	*459.40 FL
4	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
5	1		*REAR WHEEL CAP RH	Scratched	346.40 FL	-	*346.40 FL
6	1		*REAR DOOR APPS LOGO	Necessary	80.00 F	-	*80.00 FS

Supplementary #1

7	1		*REAR BUMPER SIDE BRACKET RH	Necessary	55.80 FL	-	*55.80 FL
---	---	--	------------------------------	-----------	----------	---	-----------

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,529.10	963.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	889.82	176.72
Total Parts (\$\$)	3,639.28	786.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,200.00	1,050.00
2	SPRAYPAINT	New	800.00	750.00
3	CHECK WIRING	New	50.00	20.00
4	TUFF KOTE	New	50.00	20.00
5	REMOVE/REFIX UPHOLSTERY REAR	New	120.00	60.00
6	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
7	TRANSFER DOOR PARTS	New	120.00	0.00
Gross Labour Cost (\$\$)			2,420.00	1,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >