



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8525H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	WHEEL DISC	TO REPAIR SEE LABOUR	1,570.55	-
1	FENDER SUB-ASSY FRONT RH	DEFORMED	945.30	945.30
1	EMBLEM SIDE PANEL (HYBRID)	NECESSARY	86.50	86.50
1	COVER FRONT BUMPER	DEFORMED	499.90	499.90
1	UNIT ASSY HEADLAMP RH	SERVICEABLE	2,637.60	-
1	SUPPORT FRONT BUMPER SIDE	NECESSARY	81.70	81.70
10	BUMPER CLIPS	NECESSARY	22.00	22.00
1	WIPER CONTAINER	DENTED	183.75	183.75
	LESS 25% DISCOUNT		-1,506.83	-454.79
			4,520.47	1,364.36
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF WHEEL DISC.		800.00	700.00
	SPRAYPAINT CHARGE.		600.00	500.00
	CHECK ALL LIGHTING.		50.00	20.00
	TUFF COAT ON AFFECTED PARTS.		50.00	20.00
	ADJUST FRONT WHEEL ALIGNMENT.		90.00	60.00
			1,590.00	1,300.00
GRAND TOTAL			6,110.47	2,664.36
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,150.00

Report Ref No. NS/INC21010662/Vucn2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.