

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010664/BNY3Q2**Date:** 15/08/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00086452102

Claimant Vehicle No : SMM1083G **Insured Vehicle No :** GBG4072E

Date of Loss: 09/10/2021 Nature of Claim: TP Claim No: SNM21D205904/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMM1083G**

Make & Model: HONDA CIVIC, 1.5 (A) Engine No: L15B74621510

Reg. Date: 17/06/2019 (Man. Year: 2019) Chassis No: MRHFC1660KT000058

Colour: Black Odometer: 58440 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/45 R17 Rear Tyre Size: 235/45 R17

Front Left Side: Goodyear 5 mm Rear Left Side: Goodyear 5 mm

Front Right Side: Goodyear 5 mm Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,198.88	3,598.32	3,600.56	50.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,150.00	600.00	1,550.00	72.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,348.88	4,198.32	5,150.56	55.09
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	9,348.88	3,200.00	6,148.88	65.77
+ GST 7.00/7.00% (S\$)	654.42	224.00	430.42	65.77
Nett Amount (S\$)	10,003.30	3,424.00	6,579.30	65.77

INSPECTION

Date of Assignment: 19/04/2022

Date Inspected: 18/10/2021 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Aug 2022)
Parts:	143	HONDA CIVIC 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM1083G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	579.90 FL	*579.90 FL
2	1		*FRONT BUMPER CENTRE GRILLE	Broken	185.20 FL	*185.20 FL
3	1		*FRONT BUMPER RH FOG LAMP	Not Damaged	289.90 FL	*- FL
4	1		*FRONT BUMPER RH FOG LAMP COVER	Broken	68.00 FL	*68.00 FL
5	1		*FRONT BUMPER LH FOG LAMP	Not Damaged	289.90 FL	*- FL
6	1		*FRONT BUMPER LH FOG LAMP COVER	Not Damaged	68.00 FL	*- FL
7	1		*FRONT BUMPER NUMBER PLATE GARNISH	Not Damaged	51.40 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT	Not Damaged	377.90 FL	*- FL
9	1		*FRONT BUMPER REINFORCEMENT GARNISH	Not Damaged	42.10 FL	*- FL
10	1		*FRONT BUMPER RH SIDE RETAINER	Necessary	10.40 FL	*10.40 FL
11	1		*FRONT BUMPER LH SIDE RETAINER	Necessary	10.40 FL	*10.40 FL
12	1		*FRONT GRILLE BASE	Broken	168.00 FL	*168.00 FL
13	1		*FRONT GRILLE MOULDING (LOWER)	Broken	109.70 FL	*109.70 FL
14	1		*FRONT GRILLE MOULDING (UPPER)	Cut	19.70 FL	*19.70 FL
15	1		*FRONT GRILLE EMBLEM	Necessary	18.50 FL	*18.50 FL
16	2		*FRONT GRILLE EMBLEM LOCK CLIPS	Necessary	6.00 FL	*6.00 FL
17	1		*FRONT GRILLE UPPER RUBBER SEAL	Necessary	26.80 FL	*26.80 FL
18	1		*RH HEADLAMP	Broken	1,299.80 FL	*1,299.80 FL
19	1		*RH HEADLAMP LOWER BRACKET	Broken	29.10 FL	*29.10 FL
20	1		*RH HEADLAMP CHROME MOULDING	Not Damaged	95.80 FL	*- FL
21	1		*LH HEADLAMP	Broken	1,299.80 FL	*1,299.80 FL
22	1		*LH HEADLAMP LOWER BRACKET	Broken	29.10 FL	*29.10 FL
23	1		*LH HEADLAMP CHROME MOULDING	Not Damaged	95.80 FL	*- FL
24	1		*AIRCON CONDENSER	Not Damaged	704.40 FL	*- FL
25	1		*RADIATOR ASSY	Not Damaged	1,110.50 FL	*- FL
26	1		*SET FRONT BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
27	1		*FRONT BUMPER LOWER SPOILER	Not Damaged	950.00 FS	*- FS
28	1		*FRONT NUMBER PLATE	Cut	70.00 FS	*30.00 FS
29	1		*RADIATOR COOLANT	Not Necessary	70.00 FS	*- FS
30	1		*FRONT BUMPER WRAP STICKER	Necessary	450.00 FS	*450.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,596.10	4,370.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,397.22	772.08
Total Parts (\$\$)	7,198.88	3,598.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS ,TO PANEL BEATING ,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS	New	800.00	400.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	800.00	200.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	60.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	30.00	0.00
5	REMOVE AND REPLACE AIRCON CONDENSER AND PIPES TO ASSIST REPAIR .TO REFILL AIRCON GAS	New	200.00	0.00
6	REMOVE AND REPLACE RADIATOR ASSY ,HOSES AND FAN ASSY TO ASSIST REPAIR TO REFILL COOLANT	New	200.00	0.00
7	CHECK ,REFOCUS AND ADJUST HEADLAMPS ASSY	New	60.00	0.00
Gross Labour Cost (\$\$)			2,150.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >