

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD	Re	ef:	CS3/ASM21010671/R1ty3e2	
	8 SHENTON WAY SINGAPORE 0688	Da	ate:	29/10/2021		
	ATTN: LOH CYNTH	AIA	Co	ode:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHD 6584B	Veh. Inspected		FBC 3822K	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S1M03K3B	Excess (\$)		0.00	
	Assign From	LOH CYNTHIA	Assign Date		18/10/2021	
2.	Vehicle Particulars & Condition					
	Make & Model	HONDA WAVE 125X A	c.c		125	
	Engine No.	HIDDEN	Year of Reg.		2008	
	Chassis No.	NF125ST0011790	Colour		BLACK	
	Odometer	56271 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	70/90-17	CORSA		3 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	90/90-17	CORSA		3 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND O/S BODY.					
5.	General Information					
	Accident Date	14/10/2021	Inspect Date / Tin	ne	18/10/2021 (04:45 PM)	
	Survey held at	RWAVE PTE LTD				
	50 BUKIT BATOK STREET 23 #02-25 MIDVIEW BUILDING SINGAPORE 659578					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$500-\$850					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					

Report Ref No. CS3/ASM21010671/R1ty3e2

Inspected By

Automotive Assessor

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

REGD Auto Consultant-SAE, Licensed Appraiser

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$