11/23/21, 4:37 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21010673/KTF3N2

Date: 23/11/2021

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNA00105082002

Claimant Vehicle

SLT3632J

Insured Vehicle No:

XE4500L

No:

Date of Loss:

14/10/2021

Nature of Claim: TP

SNM21D205878/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLT3632J Reg No:

PORSCHE CAYMAN, 2.7 (A) Make & Model: Engine No: 65717057

Reg. Date: 23/10/2007 (Man. Year: 2007) Chassis No: WP0ZZZ98Z7U755591

Colour: Metalic Light Grey Odometer: 86276 km

Engine Capacity: 2687 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 235/40ZR18 Rear Tyre Size: 275/35ZR18 Front Left Side: Pirelli 8 mm Rear Left Side: Pirelli 8 mm Front Right Side: Pirelli 8 mm Rear Right Side: Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		24,261.80	12,801.50	11,460.30	47.24
Miscellaneous Items		0.00	0.00	0.00	
Labour		6,500.00	2,700.00	3,800.00	58.46
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	30,761.80	15,501.50	15,260.30	49.61
	Approved Total (Overridden) (S\$)		12,000.00		
	Nett Amount (S\$)	30,761.80	12.000.00	18.761.80	60.99

INSPECTION

Date of Assignment: 18/10/2021

Poon Siang Seow (HQ) Date Inspected:

160 Sin Ming Drive, #05-13 Sin Ming AutoCity 18/10/2021 Inspected At:

Singapore 575722

Estimated Period of Repair: 7.0 days

DENISE TAY KWEE CHENG Adjuster: KENNETH KONG Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Nov 2021)

Parts: M1-COUPE PORSCHE CAYMAN 2.7 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLT3632J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

1				
	*REAR BUMPER	Cracked	2,981.80 F	*2,499.00 FL
2	*REAR BUMPER BRACKET	Repair	120.00 F	*- FL
1	*REAR FENDER	Bent	7,850.00 F	*6,300.00 FL
1	*REAR FENDER VENT GRILLE	Serviceable	450.00 F	*- FL
1	*FRONT DOOR	Repair	6,800.00 F	*- FL
1	*FRONT DOOR OUTER HANDLE	Serviceable	450.00 F	*- FL
1	*REAR WHEEL RIM	Dented	2,500.00 F	*2,500.00 FL
1	*REAR KNUCKLE ARM	Bent	780.00 F	*780.00 FL
1	*LOWER ARM	Distorted	650.00 F	*650.00 FL
1	*SHOCK ABSORBER	Bent	680.00 F	*680.00 FL
1	*BEARING	Necessary	450.00 F	*326.00 FL
1	*TYRES (80%)	Cut	550.00 FS	*440.00 FS
nchise part. S=SpcNe	ett. L=ListItemDisc.			
		Sub Total (S\$)	24,261.80	14,175.00
	- List Item Discount on L Items	s 0.00/10.00% (S\$)	0.00	1,373.50
		Total Parts (S\$)	24,261.80	12,801.50
1 1 1 1 1 1 1		*REAR FENDER *REAR FENDER VENT GRILLE *FRONT DOOR *FRONT DOOR OUTER HANDLE *REAR WHEEL RIM *REAR KNUCKLE ARM *LOWER ARM *SHOCK ABSORBER *BEARING *TYRES (80%) hise part. S=SpcNett. L=ListItemDisc.	*REAR FENDER *REAR FENDER VENT GRILLE Serviceable *FRONT DOOR Repair *FRONT DOOR OUTER HANDLE Serviceable *REAR WHEEL RIM Dented *REAR KNUCKLE ARM Bent *LOWER ARM Distorted *SHOCK ABSORBER BEARING *BEARING *TYRES (80%) Cut hise part. S=SpcNett. L=ListItemDisc. Sub Total (S\$) - List Item Discount on L Items 0.00/10.00% (S\$)	*REAR FENDER *REAR FENDER VENT GRILLE Serviceable 450.00 F *FRONT DOOR *FRONT DOOR OUTER HANDLE Serviceable 450.00 F *REAR WHEEL RIM Dented 2,500.00 F *REAR KNUCKLE ARM Bent 780.00 F *REAR KNUCKLE ARM Distorted 650.00 F *SHOCK ABSORBER Bent 680.00 F *BEARING Necessary 450.00 F *TYRES (80%) Cut 550.00 FS hise part. S=SpcNett. L=ListItemDisc. Sub Total (\$\$) - List Item Discount on L Items 0.00/10.00% (\$\$) 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING REMOVE GLASS	New	3,500.00	1,200.00
2	SPRAY PAINTING	New	1,800.00	1,200.00
3	RUST PROOFING (NPA)	New	0.00	0.00
4	TO REMOVE N REFIT UNDERCARRIAGES (NPA)	New	0.00	0.00
5	WHEEL ALIGNMENT ECT	New	1,200.00	300.00
		Gross Labour Cost (S\$)	6,500.00	2,700.00
	Report was unsul	omitted during this print-out.		

< END OF ESTIMATES >