

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21010674/KTF3N2**Date:** 28/01/2022**REFERENCE**

Insured/Claimant:	THIERRY PAUL HENRI FORICHON	Policy No:	DMPCSNW00143742104		
Date of Loss:	10/10/2021	Nature of Claim:	OD	Claim No:	SNM21D205843/C01/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJW74Y	Engine No:	CNC037457
Make & Model:	AUDI A5, 2.0 (A)	Chassis No:	WAUZZZ8R1EA075437
Reg. Date:	31/07/2014 (Man. Year: 2014)	Odometer:	112003 km
Colour:	Metallic Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$75,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55R19	Rear Tyre Size:	235/55R19
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,935.75	6,144.25	10,791.50	63.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,090.00	1,820.00	2,270.00	55.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,025.75	7,964.25	13,061.50	62.12
Approved Total (Overridden) (S\$)		6,150.00		
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	20,225.75	5,350.00	14,875.75	73.55
+ GST 7.00/7.00% (S\$)	1,415.80	374.50	1,041.30	73.55
Nett Amount (S\$)	21,641.55	5,724.50	15,917.05	73.55

INSPECTION

Date of Assignment:	18/10/2021	S Three Automotive Recovery Pte Ltd (HQ)
Date Inspected:	19/10/2021 Inspected At:	Blk 8 Sin Ming Industrial Estate, #01-64/66 Sector C
Estimated Period of Repair:	5.0 days	Singapore 575643

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 26 Jan 2022)	
Parts:	N/A	AUDI A5 2.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJW74Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE (WCP)	Bent	2,400.00 F	*1,600.00 F
2	1		*TAILGATE LOGO (WCP)	Necessary	60.00 F	*60.00 F
3	1		*TAILGATE EMBLEM 4TFSI (WCP)	Necessary	40.00 F	*40.00 F
4	1		*TAILGATE EMBLEM Q5 (WCP)	Necessary	50.00 F	*50.00 F
5	1		*TAILGATE RUBBER BEADING (WCP)	Cut	120.00 F	*120.00 F
6	1		*TAILGATE INNER TRIM BOARD (WCP)	Serviceable	250.00 F	*- F
7	1		*TAILGATE GLASS WITH MOULDING (WCP)	Not Necessary	890.00 F	*- F
8	1		*TAILLAMP RH (WCP)	Cracked	700.00 F	*420.00 F
9	1		*TAILLAMP INNER COVER (WCP)	Serviceable	35.00 F	*- F
10	1		*REAR BUMPER (WCP)	Bent	900.00 F	*680.00 F
11	1		*REAR BUMPER LOWER (WCP)	Cracked	305.00 F	*305.00 F
12	1		*REAR BUMPER WIRING HARNESS FAN SENSOR (WCP)	Cut	480.00 F	*480.00 F
13	1		*REAR BUMPER REFLECTOR RH (WCP)	Broken	200.00 F	*130.00 F
14	1		*REAR BUMPER INNER SPONGE (WCP)	Cracked	100.00 F	*100.00 F
15	1		*REAR BUMPER INNER PLASTIC (WCP)	Cracked	120.00 F	*120.00 F
16	1		*REAR BUMPER BRACKET LH (WCP)	Repair	40.00 F	*- F
17	1		*REAR BUMPER BRACKET RH (WCP)	Distorted	40.00 F	*40.00 F
18	1		*REAR BUMPER RETAINER LH (WCP)	Serviceable	40.00 F	*- F
19	1		*REAR BUMPER RETAINER RH (WCP)	Serviceable	40.00 F	*- F
20	1		*REAR BUMPER TOWING COVER (WCP)	Serviceable	50.00 F	*- F
21	1		*REAR BUMPER LOWER COVER CENTRE (WCP)	Serviceable	280.00 F	*- F
22	1		*REAR BUMPER REINFORCEMENT (WCP)	Bent	450.00 F	*450.00 F
23	1		*REAR END PANEL (WCP)	Bent	400.00 F	*400.00 F
24	1		*REAR END PANEL INNER (WCP)	Repair	400.00 F	*- F
25	1		*REAR END PANEL INNER CROSSMEMBER (WCP)	Repair	500.00 F	*- F
26	1		*REAR END INNER CHROME PANEL (WCP)	Serviceable	180.00 F	*- F
27	1		*EXHAUST PIPE CENTRE (WCP)	Repair	1,800.00 F	*- F

Report was unsubmitted during this print-out.

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRENGTHEN & PANEL BEAT ACCIDENT AREA	New	1,400.00	700.00
2	SPRAY PAINTING ON AFFECTED AREA	New	1,400.00	800.00
3	R&R TAILGATE COMPONENTS	New	180.00	60.00
4	R&R AND RESET REVERSE SENSOR	New	150.00	60.00
5	R&R EXHAUST PIPE SYSTEM	New	280.00	0.00
6	R&R INNER TRIM & CARPET TO REPAIR	New	150.00	60.00
7	RESPRAY KOTE TUFF ON ACCIDENT AREA	New	180.00	0.00
8	CHECK WIRING SYSTEM	New	80.00	20.00
9	R&R REAR TAILGATE GLASS	New	150.00	120.00
10	R&R CARPET,SEATS & TRIM TO ASSIST REPAIR	New	120.00	0.00
Gross Labour Cost (\$\$)			4,090.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >