

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010675/ATF3N2**Date:** 06/04/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00040522100		
Claimant Vehicle No :	GBE23J	Insured Vehicle No :	YN4459P		
Date of Loss:	09/10/2021	Nature of Claim:	TP	Claim No:	SNM21D205906/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE23J		
Make & Model:	TOYOTA HIACE, 3.0 D DX (A)	Engine No:	1KD2427931
Reg. Date:	26/12/2014 (Man. Year: 2014)	Chassis No:	KDH2010146398
Colour:	White	Odometer:	198969 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15C	Rear Tyre Size:	195R15C
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,035.71	820.00	4,215.71	83.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,780.00	710.00	1,070.00	60.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,815.71	1,530.00	5,285.71	77.55
Approved Total (Overridden) (\$\$)		1,200.00		
Nett Amount (\$\$)	6,815.71	1,200.00	5,615.71	82.39

INSPECTION

Date of Assignment:	18/10/2021		
Date Inspected:	20/10/2021	Inspected At:	Zero Gravity (Kaki Bukit) 2 Kaki Bukit Ave 2, #01-25 Kaki Bukit Autohub Singapore 417921
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Apr 2022)
Parts:	213	TOYOTA HIACE 3.0 D DX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE23J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLIGHT (L/H)	Cracked	569.23 FL	*569.23 FL
2	1		*WASHER TANK	Deformed	148.02 FL	*148.02 FL
3	2		*WASHER TANK MOTOR	Not Necessary	504.40 FL	*- FL
4	1		*BONNET	Repair	667.15 FL	*- FL
5	1		*LOGO	Necessary	83.69 FL	*83.69 FL
6	1		*CORNER PANEL (L/H)	Dented	292.40 FL	*292.40 FL
7	1		*STEP GARNISH (L/H)	Not Necessary	259.35 FL	*- FL
8	1		*DOOR (L/H/F)	Not Necessary	1,824.25 FL	*- FL
9	1		*DOOR HINGE (L/H LOWER)	Not Necessary	82.30 FL	*- FL
10	1		*DOOR HINGE (L/H UPPER)	Not Necessary	82.30 FL	*- FL
11	1		*FRONT GRILLE TOP GARNISH	Not Necessary	160.23 FL	*- FL
12	1		*FRONT GRILLE INNER	Not Necessary	446.12 FL	*- FL
13	1		*FRONT GRILLE OUTER (LOWER)	Not Necessary	292.32 FL	*- FL
14	4		*FRONT GRILLE CLIP	Not Necessary	20.00 FL	*- FL
15	1		*FRONT BUMPER	Not Necessary	569.89 FL	*- FL
16	6		*BUMPER CLIP	Not Necessary	36.00 FL	*- FL
17	1		*FOG LAMP COVER (L/H)	Not Necessary	68.25 FL	*- FL
18	1		*BUMPER GRILLE	Not Necessary	356.25 FL	*- FL
19	1		*BUMPER SIDE RETAINER (L/H/F)	Not Necessary	133.20 FL	*- FL
20	1		*GARNISH (WIRE HARNESS)	Not Necessary	85.60 FL	*- FL
21	1		*DOOR STICKER	Not Necessary	25.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,705.95	1,093.34
- List Item Discount on L Items 25.00/25.00% (\$)	1,670.24	273.34
Total Parts (\$)	5,035.71	820.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING SYSTEM,FOCUS LIGHTINGS	New	60.00	30.00
2	TO REMOVE AND REFIT COMPONENTS/FACILITTAE THE REPAIR	New	120.00	0.00
3	TO PROVIDE UNDER TURFCOAT	New	150.00	30.00
4	PANEL BEAT & REPAIR FRONT DAMAGE	New	750.00	350.00
5	TO PUTTY AND RE-SPRAY AFFECTED PORTION	New	700.00	300.00
Gross Labour Cost (\$)			1,780.00	710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >