



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2107463

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 29/10/2021
Reference CC4/FCI21010678/Uga3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. GV 4664J
Insured Veh. GBF 6510A
Claim No. D21002898MCVP
Policy No.
Accident Date 13/10/2021
Inspection Date 18/10/2021

Description	Total
Survey Inspection	238.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	238.00
GST (7%)	16.66
Grand Total	254.66

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21010678/Uga3q2	
			Date: 29/10/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBF 6510A	Veh. Inspected	GV 4664J
	Policy No.		Coverage (\$)	0.00
	Claim No.	D21002898MCVP	Excess (\$)	0.00
	Assign From	ESTHER	Assign Date	18/10/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA LITEACE (M)	c.c	2184
	Engine No.	HIDDEN	Year of Reg.	2002
	Chassis No.	CR425000107	Colour	SILVER
	Odometer	494505 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	165 R13	YOKOHAMA	6 mm
	L/H Front Tyre	165 R13	YOKOHAMA	6 mm
	R/H Rear Tyre	165 R13	YOKOHAMA	6 mm
	L/H Rear Tyre	165 R13	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	13/10/2021	Inspection Date	18/10/2021
	Survey held at	JIN AUTO SERVICES PTE LTD BLK 14 DEFU LANE 10 #01-412 SINGAPORE 539195		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GV 4664J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DISTORTED	394.50	394.50
1	FRONT BUMPER RH COVER	NOT NECESSARY	134.80	-
1	FRONT RH HEADLAMP RH	CRACKED	118.70	118.70
1	RH SIDELAMP	BROKEN	196.10	196.10
1	RH HEADLAMP	NOT NECESSARY	618.10	-
1	FRONT RH FENDER	BENT / BUCKLED	470.40	470.40
	LESS 25% DISCOUNT		-483.15	-294.93
			1,449.45	884.77
	<u>SPECIAL NETT ITEMS</u>			
5	FRONT BUMPER CLIPS @\$4.10 (SN)	NECESSARY	20.50	20.50
			20.50	20.50
	<u>LABOUR</u>			
	SPRAY PAINTING.		680.00	200.00
	LABOUR CHARGE.		600.00	380.00
	TUFF KOTE.		80.00	30.00
	WIRING CHECK .		30.00	20.00
			1,390.00	630.00
	GRAND TOTAL		2,859.95	1,535.27
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,200.00

Report Ref No. CC4/FCI21010678/Uga3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GV 4664J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GV 4664J

RE-INSPECTION

