



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2200397

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 18/01/2022
Reference CC3/CTI21010680/Vra3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHD 1679U
Insured Veh. GBD 4635Y
Claim No. SNM21D205940/LKKDS
Policy No. DMCVSNW00102662000
Accident Date 18/10/2021
Inspection Date 18/10/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI21010680/Vra3q2 Date: 18/01/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBD 4635Y	Veh. Inspected	SHD 1679U
	Policy No.	DMCVSNW00102662000	Coverage (\$)	0.00
	Claim No.	SNM21D205940/LKKDS	Excess (\$)	0.00
	Assign From		Assign Date	18/10/2021
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI IONIQ	c.c	1580
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	KMHC851CVLU240859	Colour	SILVER
	Odometer	56588 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	MICHELIN	5 mm
	L/H Front Tyre	195/65 R15	MICHELIN	5 mm
	R/H Rear Tyre	195/65 R15	MICHELIN	5 mm
	L/H Rear Tyre	195/65 R15	MICHELIN	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	18/10/2021	Inspection Date	18/10/2021
	Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1679U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	BENT	2,253.80	2,253.80
1	BONNET INSULATOR	SERVICEABLE	230.10	-
1	BONNET LOCK	SERVICEABLE	127.30	-
2	BONNET HINGE O/S & N/S @\$118.70	SERVICEABLE	237.40	-
1	BONNET WEATHERSTRIP	SERVICEABLE	61.30	-
1	FRONT BUMPER	CUT	430.90	430.90
1	FRONT BUMPER CENTRE GRILLE COVER -UPPER	TO REPAIR SEE LABOUR	108.50	-
1	FRONT BUMPER EMBLEM 'HYUNDAI'	SERVICEABLE	28.00	-
1	FRONT BUMPER O/S SIDE UPPER BRACKET	NECESSARY	12.00	12.00
2	FRONT BUMPER O/S & N/S SIDE RETAINER @\$39.30	NECESSARY	78.60	78.60
1	FRONT BUMPER O/S FOG LAMP	SERVICEABLE	642.50	-
2	FRONT BUMPER O/S FOG LAMP MOULDING @\$93.00	SCRATCHED	186.00	93.00
1	FRONT O/S HEADLAMP	CRACKED	1,198.80	1,198.80
1	FRONT O/S FENDER	DEFORMED	490.70	490.70
1	FRONT O/S FENDER INNER SHIELD	DISTORTED	114.70	114.70
1	FRONT N/S & O/S FENDER GARNISH -DELTA	SERVICEABLE	15.30	-
1	FRONT N/S FENDER EMBLEM 'BLUE-DRIVE'	NECESSARY	26.20	26.20
1	FRONT N/S & O/S ABSORBER MOUNTING	SERVICEABLE	105.00	-
1	FRONT N/S & O/S WHEELHUB ASSY	SERVICEABLE	153.00	-
1	FRONT N/S & O/S ABSORBER BEARING	SERVICEABLE	34.00	-
1	FRONT N/S & O/S LOWER ARM	SERVICEABLE	439.00	-
1	FRONT N/S & O/S ABSORBER	SERVICEABLE	330.00	-
1	FRONT N/S & O/S TIE ROD END	SERVICEABLE	61.00	-
1	FRONT N/S & O/S KNUCKLE ARM	SERVICEABLE	547.00	-
1	FRONT N/S & O/S KNUCKLE ARM BEARING	SERVICEABLE	109.00	-
1	FRONT N/S & O/S RIM	TO REPAIR SEE LABOUR	246.00	-
1	FRONT N/S & O/S STABILIZER LINK	SERVICEABLE	86.00	-
1	FRONT O/S WHEEL COVER	SCRATCHED	116.00	116.00
1	WASHER TANK (ADDITIONAL)	DENTED	57.50	57.50

Report Ref No. CC3/CTI21010680/Vra3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-1,705.12	-974.44
			6,820.48	3,897.76
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET FRONT O/S FENDER INNER SHIELD CLIPS (SN)	NECESSARY	28.00	28.00
1	SUNDRY (SN)	SERVICEABLE	50.00	-
			126.00	76.00
	<u>LABOUR</u>			
	TO CHECK WIRING ON HEADLAMP.		50.00	30.00
	TO ADJUST & FOCUS HEAD LAMPS.		80.00	30.00
	TO CHECK FOR FRONT O/S WHEEL ALIGNMENT.		80.00	60.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE SAME.INCLUSIVE OF THE REPAIR OF FRONT BUMPER CENTRE GRILLE COVER -UPPER AND FRONT N/S & O/S RIM .		800.00	540.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,FRONT O/S FENDER BONNET ,FRONT DOOR RH .		900.00	810.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		80.00	30.00
	DOOR STICKER RH .		50.00	50.00
			2,040.00	1,550.00
GRAND TOTAL			8,986.48	5,523.76

RECOMMENDED COST OF REPAIRS			5,523.76
------------------------------------	--	--	-----------------

Report Ref No. CC3/CT121010680/Vra3q2

THEVAN THOMAS KARTHIKESAVAN

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 1679U

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 1679U

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 1679U

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

