

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21010684/GGA3Q2**Date:** 17/01/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0000326_01

Claimant Vehicle No : GBK6894R **Insured Vehicle No :** SMC8694A

Date of Loss: 14/10/2021 Nature of Claim: TP Claim No: MFL2021D0004532

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK6894R	Engine No:	1GD8597064
Make & Model:	TOYOTA HIACE, 2.8 D DX (A)	Chassis No:	GDH2012013945
Reg. Date:	20/10/2020 (Man. Year: 2020)	Odometer:	31568 km
Colour:	Silver		
Engine Capacity:	2754 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/80 R15	Rear Tyre Size:	195/80 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,902.07	805.60	11,096.47	93.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,650.00	400.00	2,250.00	84.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,552.07	1,205.60	13,346.47	91.72
Approved Total (Overridden) (S\$)		950.00		
Nett Amount (S\$)	14,552.07	950.00	13,602.07	93.47
+ Car Rental (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,137.45		
Global Sum Settlement (S\$)		1,100.00		

INSPECTION

Date of Assignment: 18/10/2021

Date Inspected: 21/10/2021 Inspected At:

AUTO BULLOX PTE LTD - ubi (HQ)
 53 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK
 Singapore 408934

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Dec 2021)
Parts:	213	TOYOTA HIACE 2.8 D DX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK6894R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	874.45 FL	*486.00 FL
2	1		*FRONT BUMPER SIDE GARNISH O/S	Not Necessary	97.45 FL	*- FL
3	2		*FRONT BUMPER BRACKET	Not Necessary	264.50 FL	*- FL
4	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	244.20 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	486.70 FL	*- FL
6	1		*FRONT BUMPER CENTRE AIR-GRILLE	Not Necessary	296.80 FL	*- FL
7	1		*RADIATOR GRILLE ASSY	Not Necessary	596.70 FL	*- FL
8	1		*FRONT HEADLAMP ASSY O/S	Cut	761.60 FL	*554.80 FL
9	1		*FRONT AIR-FILTER HOUSING ASSY	Not Necessary	625.80 FL	*- FL
10	1		*AIR-FILTER	Not Necessary	42.80 FL	*- FL
11	1		*FRONT TOP CORNER PANEL O/S	Not Necessary	245.70 FL	*- FL
12	1		*FRONT WING MIRROR ASSY O/S	Not Necessary	495.50 FL	*- FL
13	1		*FRONT DOOR O/S	Repair	1,445.80 FL	*- FL
14	1		*FRONT DOOR OUTER GLASS MOULDING O/S	Not Necessary	215.45 FL	*- FL
15	1		*FRONT DOOR INNER GLASS CHANNEL O/S	Not Necessary	415.80 FL	*- FL
16	1		*FRONT DOOR INNER TRIMBOARD O/S	Not Necessary	784.10 FL	*- FL
17	1		*FRONT DOOR INNER RUBBER O/S	Not Necessary	392.45 FL	*- FL
18	1		*FRONT DOOR INNER LOWER RUBBER	Not Necessary	289.90 FL	*- FL
19	1		*FRONT DOOR INNER LOCK ASSY O/S	Not Necessary	474.54 FL	*- FL
20	1		*FRONT DOOR POWER WINDOW MOTOR ASSY O/S	Not Necessary	681.45 FL	*- FL
21	1		*FRONT DOOR TOP HINGE O/S	Not Necessary	145.60 FL	*- FL
22	1		*FRONT DOOR LOWER HINGE O/S	Not Necessary	125.70 FL	*- FL
23	1		*FRONT DOOR CHANNEL LINKAGE O/S	Not Necessary	98.70 FL	*- FL
24	1		*FRONT DOOR PILLAR INNER O/S	Not Necessary	771.35 FL	*- FL
25	1		*FRONT DOOR PILLAR OUTER O/S	Not Necessary	795.34 FL	*- FL
26	1		*FRONT FLOOR PANEL O/S	Not Necessary	1,972.35 FL	*- FL
27	1		*FRONT FLOOR PANEL CARPET	Not Necessary	581.45 FL	*- FL
28	1		*FRONT STEP PANEL O/S	Not Necessary	372.45 FL	*- FL
29	1		*SET FRONT NUMBER PLATE W/GARNISH	Not Necessary	55.00 FS	*- FS
30	1		*FRONT DOOR COMPANY REG STICKER	Necessary	45.00 FS	*25.00 FS
31	1		*RADIATOR COOLANT	Not Necessary	86.00 FS	*- FS
32	1		*FRONT STEP PANEL GARNISH O/S	Not Necessary	256.80 FL	*- FL
33	1		*FRONT ARCH PANEL O/S	Not Necessary	472.40 FL	*- FL
34	1		*FRONT ARCH PANEL GARNISH COVER O/S	Not Necessary	297.60 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,807.43	1,065.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,905.36	260.20
Total Parts (\$\$)	11,902.07	805.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REPLACE ,RE-ALIGN & INSTALL AFFECTED FRONT & SIDE DAMAGED AREAS	New	1,000.00	200.00
2	TO PUTTY ,PREP & RE-SPRAY ON AFFECTED FRONT & SIDE DAMAGED AREAS	New	1,000.00	200.00
3	TO REMOVE & TRANSFER FRONT DOORS COMPONENTS ,TO FACILITATE REPAIRS	New	150.00	0.00
4	TO DISCHARGE & TOP UP AC GAS	New	150.00	0.00
5	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	150.00	0.00
6	TO APPLY UNDERCOATING ON THE AFFECTED DAMAGED AREAS	New	200.00	0.00
Gross Labour Cost (\$\$)			2,650.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >