

AUTO BULLOX PTE.LTD

53 Ubi Avenue 1 #01-25 Paya Ubi Industrial Park S(408934)

Business Reg No: 201919765N
Tel: 6841 5383 / Fax: 6841 6043
E-Mail: autobullox@gmail.com

To: Motor Claims Department

Date: 18/10/2021

Vehicle No: GBK6894R
Model: Toyota Hiace

Estimated Repair Cost For GBK6894R (Toyota Hiace)

QTY	Parts	Amount
1	Front bumper <i>CRA</i>	\$ 874.45 486
1	Front bumper side garnish o/s X	\$ 97.45
2	Front bumper bracket @ SGD 132.25 X	\$ 264.50
2	Front bumper side retainer @ SGD 122.10 X	\$ 244.20
1	Front bumper reinforcement X	\$ 486.70
1	Front bumper centre air-grille X	\$ 296.80
1	Radiator grille assy X	\$ 596.70
1	Front headlamp assy o/s X <i>cut</i>	\$ 761.60 554.8
1	Front air-filter housing assy X	\$ 625.80
1	Air-filter X	\$ 42.80
1	Front top corner panel o/s X	\$ 245.70
1	Front wing mirror assy o/s X	\$ 495.50
1	Front door o/s X <i>repair</i>	\$ 1,445.80
1	Front door outer glass moulding o/s X	\$ 215.45
1	Front door inner glass channel o/s X	\$ 415.80
1	Front door inner trimboard o/s X	\$ 784.10
1	Front door inner rubber o/s X	\$ 392.45
1	Front door inner lower rubber X	\$ 289.90
1	Front door inner lock assy o/s X	\$ 474.54
1	Front door power window motor assy o/s X	\$ 681.45
1	Front door top hinge o/s X	\$ 145.60
1	Front door lower hinge o/s X	\$ 125.70
1	Front door channel linkage o/s X	\$ 98.70
1	Front door pillar inner o/s X	\$ 771.35
1	Front door pillar outer o/s X	\$ 795.34
1	Front floor panel o/s X	\$ 1,972.35
1	Front floor panel carpet X	\$ 581.45
1	Front step panel o/s X	\$ 372.45
1	Front step panel garnish o/s X	\$ 256.80
1	Front arch panel o/s X	\$ 472.40
1	Front arch panel garnish cover o/s X	\$ 297.60
Parts Sum: \$		15,621.43 1040.8
Parts Less 25% : \$		3,905.35
Parts Total: \$		11,716.07 780.6
Special Nett Items		
1 set	Front Number Plate W/Garnish X	\$ 55.00
1	Front Door Company Reg Sticker X	\$ 45.00 25
1	Radiator coolant X	\$ 86.00
Special Nett Items Total: \$		186.00

Labour & Misc Charges

Description			
To Remove, Replace, Re-align & Install affected Front & Side Damaged Areas	\$	1,000.00	200
To Putty, Prep & Re-spray on affected Front & Side Damaged Areas	\$	1,000.00	200
To Remove & Transfer Front Doors Components, to Facilitate Repairs	\$	150.00	X
To Discharge & Top Up AC Gas	\$	150.00	X
To Conduct Computerize Full Wheel Alignment	\$	150.00	X
To Apply Undercoating on the Affected Damaged Areas	\$	200.00	X
Labour Charges Total:	\$	2,650.00	

Parts Total: \$ 11,716.07
Special Nett Items Total: \$ 186.00
Labour Charges Total: \$ 2,650.00
Total Cost Of Repair: \$ 14,552.07
 (Non-Inclusive of GST)

2 Days.
 L/S
 After repair photos
 Gmo Rty.
 21/10/21.

1205.6
 -20%: 950

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from the Insurance Company

Acknowledged by Repairer
 Signature:
 Date: