

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21010685/VTF3E2

Date: 19/11/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00157422000
Claimant Vehicle No: SLH5112T Insured Vehicle No: SKW1315J
Date of Loss: 14/10/2021 Nature of Claim: TP Claim No: SNM21D205886/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLH5112T
Make & Model: TOYOTA WISH, 1.8 CVT (A) Engine No: 2ZR1838334
Reg. Date: 08/11/2016 (Man. Year: 2016) Chassis No: JTDGG20W10J005356
Colour: Silver Odometer: 343861 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Giti 6 mm Rear Left Side: Giti 6 mm
Front Right Side: Giti 6 mm Rear Right Side: Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,665.67	4,119.11	5,546.56	57.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,560.00	1,640.00	2,920.00	64.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,225.67	5,759.11	8,466.56	59.52
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	14,225.67	4,500.00	9,725.67	68.37
+ GST 7.00/7.00% (S\$)	995.80	315.00	680.80	68.37
Nett Amount (S\$)	15,221.47	4,815.00	10,406.47	68.37

INSPECTION

Date of Assignment: 18/10/2021
Date Inspected: 19/10/2021 Inspected At: Teamwork Garage Pte Ltd (HQ)
53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park
Singapore 408934
Estimated Period of Repair: 5.0 days

Adjuster: Thevan Thomas Karthikesavan

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Nov 2021)
Parts:	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH5112T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	765.50 FL	*543.90 FL
2	2		*REAR BUMPER RETAINER	Cut	151.20 FL	*151.20 FL
3	2		*REAR BUMPER BRACKET	Necessary	120.30 FL	*120.30 FL
4	2		*REAR BUMPER REFLECTOR	Cracked	173.60 FL	*136.00 FL
5	2		*REAR BUMPER DAMPER	Not Necessary	192.30 FL	*- FL
6	1		*KEYLESS SENSOR	Deformed	281.60 FL	*144.20 FL
7	1		*KEYLESS SENSOR HOLDER	Not Necessary	102.20 FL	*- FL
8	1		*TAILGATE	Dented	1,370.62 FL	*1,275.00 FL
9	1		*TAILGATE WEATHERSTRIP	Serviceable	229.10 FL	*- FL
10	1		*TAILGATE LOCK	Jammed	509.20 FL	*361.00 FL
11	1		*TAILGATE LOCK STRIKER	Serviceable	53.17 FL	*- FL
12	1		*TAILGATE EMBLEM - VALVE MATIC (2PCS)	Necessary	54.59 FL	*54.59 FL
13	1		*TAILGATE EMBLEM - LOGO	Necessary	65.29 FL	*65.29 FL
14	1		*TAILGATE GLASS MOULDING	Necessary	180.00 FL	*180.00 FL
15	1		*TAILGATE OUTER CHROME GARNISH	Cracked	386.50 FL	*239.00 FL
16	2		*TAILGATE LAMP	Serviceable	854.56 FL	*- FL
17	1		*TAILGATE INNER TRIM BOARD	Cut	331.90 FL	*299.70 FL
18	2		*TAILLAMP	Scratched	1,054.76 FL	*643.00 FL
19	2		*TAILLAMP BRACKET	Not Necessary	360.60 FL	*- FL
20	1		*END PANEL	Dented	803.87 FL	*420.00 FL
21	1		*END PANEL TOP GARNISH	Cut	382.61 FL	*218.97 FL
22	1		*SPARE TYRE COMPARTMENT	Serviceable	1,203.60 FL	*- FL
23	1		*WIPER MOTOR (JAMMED)	Not Consistent With The Impact	687.12 FL	*- FL
24	1		*WIPER BLADE	Serviceable	46.47 FL	*- FL
25	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*20.00 FS
26	2		*SET REAR FENDER INNER TRIM CLIP	Necessary	120.00 FS	*30.00 FS
27	1		*SET TAILGATE INNER TRIM BOARD CLIP	Necessary	60.00 FS	*20.00 FS
28	1		*SET REAR BUMPER TOP RUBBER	Necessary	200.00 FS	*100.00 FS
29	1		*SET REAR NUMBER PLATE	Necessary	80.00 FS	*50.00 FS
30	1		*SET WINDSCREEN SEALANT	Necessary	120.00 FS	*60.00 FS
31	1		*SET REVERSE SENSOR	Cut	400.00 FS	*200.00 FS
32	1		*REVERSE CAMERA (CUT)	Not Consistent With The Impact	500.00 FS	*- FS
33	1		*SPARE TYRE TOP BOARD	Repair	500.23 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	12,380.89	5,332.15
- List Item Discount on L Items 25.00/25.00% (S\$)	2,715.22	1,213.04
Total Parts (S\$)	9,665.67	4,119.11

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND LIGHTNING SYSTEM	New	60.00	30.00
2	REMOVE TRIMS & GARNISHES	New	200.00	30.00
3	REMOVE AND REFIT EXHAUST SILENCER	New	150.00	0.00
4	REMOVE, REFIT REAR WINDSCREEN	New	200.00	120.00
5	REMOVE, REFIT AND REPLACE REVERSE SENSOR	New	200.00	30.00
6	PANEL BEATING ON AFFECTED AREAS	New	1,800.00	600.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	1,800.00	800.00
8	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	30.00
Gross Labour Cost (\$)			4,560.00	1,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >