

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21010689/UQF3N2**Date:** 05/11/2021**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/21-516469-WTT
Claimant Vehicle No :	PC3697P	Insured Vehicle No :	FBN5976D
Date of Loss:	15/10/2021	Nature of Claim:	TP
		Claim No:	MSC/V/21-000459

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC3697P	Engine No:	1KD2481957
Make & Model:	TOYOTA HIACE, 3.0 COMMUTER GL (A)	Chassis No:	KDH2230022697
Reg. Date:	10/04/2015 (Man. Year: 2015)	Odometer:	432565 km
Colour:	Gold		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	195R15
Front Left Side:	GREEN-MAX 6 mm	Rear Left Side:	GREEN-MAX 6 mm
Front Right Side:	GREEN-MAX 6 mm	Rear Right Side:	GREEN-MAX 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,120.30	1,208.42	3,911.88	76.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,380.00	1,320.00	1,060.00	44.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,500.30	2,528.42	4,971.88	66.29
Approved Total (Overridden) (\$\$)		2,000.00		
(\$\$)	7,500.30	2,000.00	5,500.30	73.33
+ GST 7.00/7.00% (\$\$)	525.02	140.00	385.02	73.33
Nett Amount (\$\$)	8,025.32	2,140.00	5,885.32	73.33

INSPECTION

Date of Assignment:	22/10/2021		
Date Inspected:	18/10/2021	Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	2.0 days		

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Nov 2021)	
Parts:	N/A	TOYOTA HIACE 3.0 COMMUTER GL (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC3697P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	2,159.10 F	*- FL
2	1		*TAILGATE REAR LOGO	Necessary	68.10 F	*68.10 FL
3	1		*TAILGATE HIACE EMBLEM	Necessary	80.50 F	*62.20 FL
4	1		*TAILGATE G.L EMBLEM	Necessary	60.00 F	*50.00 FL
5	1		*REAR BUMPER	Deformed/Warped	681.00 F	*681.00 FL
6	1		*REAR BUMPER SIDE RETAINER O/S	Cracked	105.00 F	*105.00 FL
7	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
8	1		*TAILLAMP O/S	Scratched	488.50 F	*366.30 FL
9	1		*TAILLAMP LOWER GARNISH O/S	Distorted	180.20 F	*150.20 FL
10	1		*TAILLAMP LOWER GARNISH BRACKET O/S	Cracked	100.30 F	*65.10 FL
11	1		*TAILLAMP HOUSING PANEL O/S	Repair	482.50 F	*- FL
12	1		*REAR END PANEL OUTER	Repair	650.10 F	*- FL
13	1		*TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,120.30	1,607.90
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	399.48
Total Parts (\$\$)	5,120.30	1,208.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX REAR REVERSE SENSOR	New	80.00	0.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
4	TO TRANSFER TAILGATE MECHANISM	New	100.00	0.00
5	TO SPRAY RUST PROOFING	New	100.00	0.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	800.00	550.00
7	TO PUTTY & SPRAY PAINTING	New	1,100.00	750.00
Gross Labour Cost (\$\$)			2,380.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >