

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010690/DTF3Q2**Date:** 09/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00089632102

Claimant Vehicle No : SMU6143S **Insured Vehicle No :** YN768Z

Date of Loss: 15/10/2021 Nature of Claim: TP Claim No: SNM21D205905/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU6143S**

Make & Model: HONDA FIT, 1.3 GF CVT (A) Engine No: L13B3938137

Reg. Date: 21/08/2020 (Man. Year: 2019) Chassis No: GK33423648

Colour: Red Odometer: 71631 km

Engine Capacity: 1317 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15

Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm

Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,570.32	3,122.63	15,447.69	83.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,000.00	1,130.00	4,870.00	81.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,570.32	4,252.63	20,317.69	82.69
Approved Total (Overridden) (S\$)		3,400.00		
Nett Amount (S\$)	24,570.32	3,400.00	21,170.32	86.16

INSPECTION

Date of Assignment: 18/10/2021

Date Inspected: 19/10/2021 Inspected At: C.s.ong Auto Pte Ltd (HQ)
10, ANG MO KIO IND PARK 2A #02-16 AMK
AUTO POINT SINGAPORE 568047
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Mar 2022)
Parts:	143	HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU6143S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	1,680.00 FL	*- FL
2	1		*BONNET INSULATOR	Not Necessary	405.00 FL	*- FL
3	2		*BONNET HINGE LH/RH	Not Necessary	170.00 FL	*- FL
4	1		*BONNET LOCK	Not Necessary	290.50 FL	*- FL
5	1		*BONNET STRIKER LOCK	Not Necessary	49.00 FL	*- FL
6	4		*BONNET SEAL	Not Necessary	120.00 FL	*- FL
7	1		*SET BONNET STOPPERS	Not Necessary	50.00 FL	*- FL
8	1		*FRONT GRILLE	Cut	402.80 FL	*402.80 FL
9	1		*FRONT GRILLE BASE	Not Necessary	427.40 FL	*- FL
10	1		*FRONT GRILLE LOGO	Dislodged	93.40 FL	*82.44 FL
11	1		*HEAD LAMP LH/RH	O/SScratched /N/SNotNecessary	2,990.00 FL	*1,170.00 FL
12	1		*HEAD LAMP LOWER BRACKET LH/RH	O/S Broken / N/SNot Necessary	190.00 FL	*68.50 FL
13	1		*HEAD LAMP WIRE HARNESS COMPLETE	Not Necessary	1,420.00 FL	*- FL
14	1		*FRONT BUMPER	Torn	817.70 FL	*584.20 FL
15	2		*FRONT BUMPER SIDE RETAINER LH/RH	Serviceable	120.80 FL	*- FL
16	1		*FRONT BUMPER LOWER GRILLE	Mtg Cracked	380.00 FL	*211.20 FL
17	1		*FRONT BUMPER TOW HOOK COVER	Cut	79.00 FL	*67.30 FL
18	1		*FRONT BUMPER FOG LAMP GARNISH LH/RH	N/SNot Necessary /O/SDislodged	597.40 FL	*98.45 FL
19	1		*FRONT BUMPER UNDERCOVER	Not Necessary	310.40 FL	*- FL
20	1		*FRONT BUMPER SPONGE	Not fitted	320.40 FL	*- FL
21	1		*FRONT REINFORCEMENT BAR	Dented	813.00 FL	*336.00 FL
22	1		*FRONT SUPPORT PANEL	Repair	1,420.00 FL	*- FL
23	1		*FRONT SUPPORT PANEL TOP GARNISH	Dislodged / Broken	125.40 FL	*125.40 FL
24	1		*A/C CONDENSOR ASSY	Not Necessary	1,504.50 FL	*- FL
25	1		*A/C CONDENSOR HIGH PRESSURE PIPE	Not Necessary	275.00 FL	*- FL
26	1		*A/C CONDENSOR LOW PRESSURE PIPE	Not Necessary	278.00 FL	*- FL
27	1		*A/C CONDENSOR DISCHARGE PIPE	Not Necessary	310.00 FL	*- FL
28	1		*RADIATOR ASSY	Not Necessary	1,850.00 FL	*- FL
29	1		*RADIATOR TOP HOSE	Not Necessary	56.80 FL	*- FL
30	1		*RADIATOR BOTTOM HOSE	Not Necessary	56.80 FL	*- FL
31	1		*RADIATOR FAN MOTOR	Not Necessary	436.00 FL	*- FL
32	1		*RADIATOR FAN BLADE	Not Necessary	278.00 FL	*- FL
33	1		*RADIATOR FAN COWLING	Not Necessary	325.00 FL	*- FL
34	1		*WIPER WASHER TANK	Not Necessary	175.00 FL	*- FL
35	1		*WIPER WASHER TANK MOTOR	Not Necessary	158.80 FL	*- FL
36	1		*WIPER WASHER TANK HOSE	Not Necessary	49.20 FL	*- FL
37	1		*AIR INTAKE DUCT	Not Necessary	148.00 FL	*- FL
38	1		*AIR INTAKE HOSE	Not Necessary	145.00 FL	*- FL
39	1		*RADIATOR SPARE TANK	Not Necessary	180.10 FL	*- FL
40	2		*FRONT FENDER LH/RH	Not Necessary	1,137.00 FL	*- FL
41	2		*FRONT FENDER INNER SHIELD LH/RH	Torn	303.00 FL	*303.00 FL
42	2		*FRONT FENDER QUARTER GLASS LH/RH	Not Necessary	536.00 FL	*- FL

Report was unsubmitted during this print-out.

3/9/22, 10:01 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	2		*FRONT FENDER QUARTER GLASS MOULDING LH/RH	Not Necessary	296.00 FL	*- FL
44	1		*FRONT LOGO BASE	Dislodged	180.00 FL	*30.00 FL
45	1		*FRONT GRILLE SIDE GARNISH LH	Broken	200.00 FL	*124.00 FL
46	1		*BONNET INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
47	1		*BONNET INSULATOR CLIPS	Not Necessary	50.00 FS	*- FS
48	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
49	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*20.00 FS
50	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
51	1		*FRONT BUMPER GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
52	1		*FRONT BUMPER UNDER COVER CLIPS	Not Necessary	50.00 FS	*- FS
53	1		*COOLANT	Not Necessary	100.00 FS	*- FS
54	1		*FRONT NO PLATE & CASING	Not Necessary	100.00 FS	*- FS
55	1		*FRONT BUMPER SENSOR	Damaged	300.00 FS	*200.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)						23,000.403,843.29
- List Item Discount on L Items 20.00/20.00% (\$)						4,430.08720.66
Total Parts (\$)						18,570.323,122.63
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,400.00	600.00
2	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,400.00	500.00
3	TO TUFF COAT DAMAGED AREAS	New	300.00	0.00
4	TO RNR A/C CONDENSOR & REFILL GAS TO FACILITATE REPAIRS	New	200.00	0.00
5	TO RNR RADIATOR ASSY & REFILL COOLANT TO FACILITATE REPAIRS	New	200.00	0.00
6	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
7	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (\$\$)			6,000.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >