

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD	Ref:	CS3/ASM21000594/Gga3q2-	
	8 SHENTON WAY	#24-01	Date:	25/05/2022	
	AXA TOWERSING				
	ATTN:ONG KIAN			: ASM	
1.					
	Insured Veh.	SHD 6970U	Veh. Inspected	GBJ 4009Z	
	Policy No.	S1M03502	Coverage (\$)	0.00	
	Claim No.	S1M03502	Excess (\$)	0.00	
	Assign From		Assign Date	13/01/2021	
2. Vehicle Particulars & Condition					
	Make & Model	NISSAN NV200 1.6	c.c	1597	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	VM20133773	Colour	BLACK	
	Odometer	22692 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	165/80 R14	TOYO	6 mm	
	L/H Front Tyre	165/80 R14	TOYO	6 mm	
	R/H Rear Tyre	165/80 R14	TOYO	6 mm	
	L/H Rear Tyre	165/80 R14	TOYO	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	06/01/2021	Inspection Date	13/01/2021	
	Survey held at	GARAGE 13 PTE LTD			
		8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days				