



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: KOH JANICE			Ref: CS/ASM21010694/Evy3e2 Date: 29/10/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 5587E	Veh. Inspected	SMQ 2320U
	Policy No.	VFX/P2413997	Coverage (\$)	0.00
	Claim No.	S1M033JJ	Excess (\$)	0.00
	Assign From	KOH JANICE	Assign Date	18/10/2021
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 316I	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	WBA3A12040J720342	Colour	SILVER
	Odometer	97405 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/50 R17	GOODYEAR	4 mm
	L/H Front Tyre	225/50 R17	GOODYEAR	4 mm
	R/H Rear Tyre	225/50 R17	GOODYEAR	4 mm
	L/H Rear Tyre	225/50 R17	GOODYEAR	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	20/02/2021	Inspection Date	19/10/2021
	Survey held at	WIN AUTOMOTIVE SERVICES BLK 6, 399J WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE SINGAPORE 678008		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	