

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21010696/VPA3Q2**Date:** 08/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900104637
Claimant Vehicle No :	SHC1150H	Insured Vehicle No :	SML8430Y
Date of Loss:	17/10/2021	Nature of Claim:	TP
		Claim No:	8735078344SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC1150H		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZRS060857
Reg. Date:	10/08/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU603563227
Colour:	Blue	Odometer:	755674 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,458.07	2,694.22	1,763.85	39.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,610.00	1,240.00	370.00	22.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,068.07	3,934.22	2,133.85	35.17
Approved Total (Overridden) (S\$)		3,150.00		
(S\$)	6,068.07	3,150.00	2,918.07	48.09
+ GST 7.00/7.00% (S\$)	424.76	220.50	204.26	48.09
Nett Amount (S\$)	6,492.83	3,370.50	3,122.33	48.09
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$125.40/day) (S\$)		376.20		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,898.70		
Global Sum Settlement (S\$)		3,800.00		

INSPECTION

Date of Assignment:	18/10/2021	
Date Inspected:	18/10/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days	

Adjuster: Thevan Thomas Karthikesavan**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT FENDER HYBRID EMBLEM RH	Necessary	86.50 FL	*86.50 FL
2	1		*FRONT FENDER SUB ASSY RH	Repair	945.30 FL	*- FL
3	1		*FRONT FENDER SHIELD RH	Serviceable	198.50 FL	*- FL
4	1		*FRT FENDER RETAINER RH	Necessary	86.30 FL	*86.30 FL
5	1		*FRONT BUMPER FOG LAMP	Serviceable	920.00 FL	*- FL
6	1		*HEADLAMP RH	Scratched	2,637.60 FL	*2,637.60 FL
7	1		*FRONT BUMPER COVER	Cut	499.90 FL	*499.90 FL
8	1		*FRONT BUMPER SIDE BRACKET RH	Necessary	82.30 FL	*82.30 FL
9	10		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
10	1		*FRT WHEEL HUB CAP RH	Scratched	177.70 FL	*177.70 FL
11	1		*FRT TYRE RH	Serviceable	216.00 FS	*- FS
					F=Franchise part. S=SpcNett. L=ListItemDisc.	
					Sub Total (\$\$)	5,872.103,592.30
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,414.03898.08
					Total Parts (\$\$)	4,458.072,694.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	900.00	700.00
2	SPRAY PAINTING CHARGE	New	600.00	500.00
3	CHECK ALL LIGHTING	New	50.00	20.00
4	TUFF KOTE	New	60.00	20.00
Gross Labour Cost (\$\$)			1,610.00	1,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >