

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21010697/KGA3Q2**Date:** 01/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700020485
Claimant Vehicle No :	SLX4099X	Insured Vehicle No :	SLP9676P
Date of Loss:	01/10/2021	Nature of Claim:	TP
		Claim No:	2557862471SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX4099X	Engine No:	R16A14002698
Make & Model:	HONDA CIVIC, 1.6 5AT (A)	Chassis No:	JHMFD46209S200684
Reg. Date:	02/11/2009 (Man. Year: 2008)	Odometer:	137862 km
Colour:	Metallic Pearl White		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45Z R17	Rear Tyre Size:	225/45Z R17
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,116.12	1,116.12	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	950.00	250.00	20.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,316.12	2,066.12	250.00	10.79
Approved Total (Overridden) (S\$)		1,650.00		
(S\$)	2,316.12	1,650.00	666.12	28.76
+ GST 7.00/7.00% (S\$)	162.13	115.50	46.63	28.76
Nett Amount (S\$)	2,478.25	1,765.50	712.75	28.76
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,947.50		

INSPECTION

Date of Assignment:	18/10/2021	
Date Inspected:	19/10/2021	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	730.20 FL	*730.20 FL
2	1		*REAR BUMPER RH RETAINER	Distorted	24.30 FL	*24.30 FL
3	1		*TAILLAMP RH	Cracked	308.70 FL	*308.70 FL
4	1		*REAR BOOT LOGO	Necessary	25.70 FL	*25.70 FL
5	1		*REAR BOOT EMBLEM (MUGEN)	Necessary	45.00 FS	*45.00 FS
6	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,333.90	1,333.90
- List Item Discount on L Items 20.00/20.00% (S\$)	217.78	217.78
Total Parts (S\$)	1,116.12	1,116.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR BUMPER ASSY ,TAILLAMP TO KNOCK & REPAIR REAR PANEL REAR BOOT ,REAR RH FENDER & REALIGN THE SAME	New	500.00	350.00
2	PUTTY & RESPRAY ON REAR PANEL ,BOOT ,REAR BUMPER ,REAR RH FENDER	New	700.00	600.00
			Gross Labour Cost (\$)	1,200.00
				950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >