Insurance Loss Adjusters and Licensed Appraiser Regn. 652868584L Blk 131 Rivervale Street #05-872 S'pore 540131 Tel:65528323 Fax:64574321

Our ref: PS/018/05/18 Date: 07th June 2018

Mr Navin Kumar A/L Asok Kumaran c/o Blk 125 Bukit Merah Lane 1 #01-168 Singapore 150125

Dear Sir,

Re: THIRD PARTY CLAIM

We refer to your instruction to appraise the vehicle JSP 6997 on 28th May 2018.

A static inspection was conducted during our survey and our report is enclosed for your perusal. The estimated repair cost submitted by **Messrs. Friendship Motor Company** for \$13,788.00 as per our attached schedule have been inspected thoroughly each and every item and revised by us against the actual damages found on the vehicle which have been recommended by us accordingly.

The repairer has agreed to undertake repairs at our revised amount of \$8,900.00 lump sum corresponding to supply of parts, labour charges and spray-painting. However, we have not given instruction to authorize the repairs.

Under normal circumstances, the estimated period of repairs would be **SEVEN** (7) days. Photographs of the damaged vehicle taken by us during our inspection are enclosed.

We are reverting the matter to you for a decision.

Please do not hesitate to contact us if you need any clarification.

Assuring you of our best services.

Yours faithfully,

PRESTIGE APPRAISER SERVICES

LOUIS S C NG CAE AMIMI Dip. MTM. Automotive Engineer Licensed Appraiser

Encl.

#### VEHICLE INSPECTION REPORT

To: Mr Navin Kumar A/L Asok Kumaran

c/o Blk 125 Bukit Merah Lane 1

#01-168

Singapore 150125

Date

: 07th June 2018 : PS/018/05/18

Our Ref

Policy No

Sum Insured

Excess

: T/P Claim

Assigned By

: Mr Navin Kumar A/L Asok Kumaran

Assignment Date Accident Date

: 28th May 2018 : 15th April 2018

Inspection Date

: 28th May 2018

Workshop Name

: Friendship Motor Company Survey Conducted At : Blk 125 Bukit Merah Lane 1

#01-168

Singapore 150125

### PARTICULARS OF VEHICLE

Registration No

: JSP 6997

Mileage

: 050533km

Make/Model

: Yamaha YZF25

Engine No

: HIDDEN

Type Of Body

: Motorcycle

Chassis No

: PMYRG150H0012201

Year Of Manu./Regn.

: 2017

Passenger Cap.

: 1 Passenger

Colour

: Blue

Others

#### **CONDITION OF TYRES**

Front Tyre

: 5mm 110/70-17 IRC

Rear Tyre

: 5mm 110/70-17 IRC

The above represent the estimated remaining life of the tyre treads.

## PRE-ACCIDENT CONDITION (Static tests only)

Handbrake

: Serviceable

Body Work

: Good

Footbrake

: Serviceable

Paint Work

: Good

Steering

: Serviceable

Others

#### POINT OF IMPACT

The vehicle sustained impacts on the front, R/H and L/H portion.

#### GENERAL DESCRIPTION OF DAMAGES

The main body frame, handle bar, fuel tank, forks, wheel rim, exhaust muffler were dented/bent.

For details of damages please refer to schedule attached.

#### REMARKS:

This survey was conducted strictly without prejudice.

Vehicl	e No: JSP 6997	Our Ref:	PS/018/05/18			
Qty	Descriptions	Conditions		Repairer's Est.		Our Revised.
0	LIST ITEMS	warped	\$	820.00	\$	820.00
2	front fork	dented	•	185.00		185.00
1	under bracket	cracked		98.00		98.00
1	R/H fairing inner garnish	dented		98.00		98.00
1	L/H fairing inner garnish	dented		620.00		620.00
1	radiator	damaged		65.00		65.00
1	radiator hose	sliced		480.00		480.00
1	front brake caliper	cracked		105.00		105.00
1	front windshield	cracked		198.00		198.00
1	front mudguard			210.00		210.00
1	headlamp fairing	broken		285.00		285.00
1	headlamp	broken		185.00		185.00
1	headlamp stay	dented		168.00		168.00
1	headlamp wire harness	damaged		68.00		68.00
1	R/H front signal lamp	cracked		68.00		68.00
1	L/H front signal lamp	cracked		68.00		68.00
1	R/H mirror	broken				68.00
1	L/H mirror	broken		68.00		85.00
1	steering cone w/bearing	necessary		85.00		128.00
1	R/H handle bar	bent		128.00		
1	L/H handle bar	bent		128.00		128.00
1	R/H handle balancer	sliced		39.00		39.00
1	L/H handle balancer	scratched		39.00		39.00
1set	handle grip	necessary		68.00		68.00
1	clutch lever	sliced		72.00		72.00
1	brake lever	sliced		72.00		72.00
1	fuel tank	dented/distorted		860.00		860.00
1	R/H fuel tank side cover	missing		140.00		140.00
1	L/H fuel tank side cover	sliced		140.00		140.00
1	front brake disc	warped		198.00		198.00
1	front wheel rim	broken		555.00		555.00
1	horn	dented		56.00		56.00
1	lower fairing	cracked		185.00		185.00
1	R/H fairing	broken		340.00		340.00
1	L/H fairing	cracked		340.00		340.00
1	R/H front foot rest	sliced		48.00		48.00
1	L/H front foot rest	sliced		48.00		48.00
1	R/H rear foot rest	sliced		48.00		48.00
1	L/H rear foot rest	sliced		48.00		48.00
1	R/H seat side cover	dented/sliced		185.00		185.00
1		sliced		185.00		185.00
1	L/H seat side cover			58.00		58.00
1	R/H front signal lamp	fractured		58.00		58.00
1	L/H front signal lamp	scratched		55.00		55.00
1	brake pedal	bent				75.00
1	gear pedal	bent		75.00		655.00
1	speedometer	cracked		655.00		325.00
1	rider seat	torn		325.00		323.00
1	rear wheel rim	serviceable		625.00		98.00
1	brake cable	damaged		98.00		
1	throttle cable	damaged		125.00		125.00
		Balance c/f		\$ 9,870.00	)	\$ 9,245.00

Vehicle	e No: JSP 6997		Our Ref:		PS/018/05/18	
Qty	Descriptions	Conditions		Repairer's Est.		Our Revised.
1	R/H engine cover brake pump	Balance b/d serviceable damaged	\$	9,870.00 225.00 168.00	\$	9,245.00 - 168.00
1 1 1	rear mudguard exhaust muffler exhaust protector	serviceable dented/sliced serviceable	,	185.00 750.00 95.00 11,293.00	55	750.00 
	CAUCTT ITEMS	Less 10%	\$	11,293.00	\$	1,016.30 9,146.70
1 1 1	S/NETT ITEMS front tyre front number plate coolant engine oil	wall cut necessary necessary necessary		300.00 25.00 40.00 80.00		200.00 22.00 40.00 60.00
	<u>Labour Charges &amp; Misc</u> To dismantle & replace damaged parts, panel beat where necessary.			950.00		750.00
	To putty, apply primer & spray-paint on the affected portion.			650.00		500.00
	To align main body frame.			400.00		320.00
	Transportation charges.		\$	50.00	\$	40.00 11,078.70

**Note:** The repairer has agreed to undertake the repairs at our adjusted amount of **\$8,900.00 lump sum** corresponding to supply of parts, labour and spray-painting charges.

Under normal circumstances, the estimated repair period would be **SEVEN (7)** days.

Pursuant to your instruction we have **not** authorised repairs on your behalf.

PRESTICE APPRAISER SERVICES

LOUIS S C NG CAE AMIMI (UK)

Licensed Appraiser

Dip. MTM. Automotive Engineer

































































































