No.

22936

Insurance Loss Adjusters and Licensed Appraisers Regn.52868584L Blk 131 Rivervale Street #05-872 S'pore 540131 Tel:65528323 Fax:64574321

INVOICE =

Customer

To

Mr Navin Kumar A/L Asok Kumaran c/o Blk 125 Bukit Merah Lane 1 #01-168 Singapore 150125 Date Our ref Your Ref 07-Jun-18 PS/018/05/18

VEHICLE REGISTRATION NO: JSP 6997

VEHICLE MAKE/MODEL

: Yamaha YZF25

INSPECTION REPORT FEES

(inclusive of photographs & transport charges)

\$570.00

DOLLARS: Five Hundred And Seventy Only

E. &. O. E.

for PRESTIGE APPRAISER SERVICES

Insurance Loss Adjusters and Licensed Appraiser Regn. 652868584L Blk 131 Rivervale Street #05-872 S'pore 540131 Tel:65528323 Fax:64574321

Our ref: PS/018/05/18 Date: 07th June 2018

Mr Navin Kumar A/L Asok Kumaran c/o Blk 125 Bukit Merah Lane 1 #01-168 Singapore 150125

Dear Sir,

Re: THIRD PARTY CLAIM

We refer to your instruction to appraise the vehicle JSP 6997 on 28th May 2018.

A static inspection was conducted during our survey and our report is enclosed for your perusal. The estimated repair cost submitted by Messrs. Friendship Motor Company for \$13,788.00 as per our attached schedule have been inspected thoroughly each and every item and revised by us against the actual damages found on the vehicle which have been recommended by us accordingly.

The repairer has agreed to undertake repairs at our revised amount of \$8,900.00 lump sum corresponding to supply of parts, labour charges and spray-painting. However, we have not given instruction to authorize the repairs.

Under normal circumstances, the estimated period of repairs would be SEVEN (7) days. Photographs of the damaged vehicle taken by us during our inspection are enclosed.

We are reverting the matter to you for a decision.

Please do not hesitate to contact us if you need any clarification.

Assuring you of our best services.

Yours faithfully,

PRESTIGE APPRAISER SERVICES

LOUIS S C NG CAE AMIMI Dip. MTM. Automotive Engineer Licensed Appraiser

Encl.

VEHICLE INSPECTION REPORT

To: Mr Navin Kumar A/L Asok Kumaran

c/o Blk 125 Bukit Merah Lane 1

#01-168

Singapore 150125

Date

: 07th June 2018 : PS/018/05/18

Our Ref Policy No

Sum Insured : Excess : T/P Claim

Assigned By

: Mr Navin Kumar A/L Asok Kumaran

Assignment Date : 28th May 2018
Accident Date : 15th April 2018
Inspection Date : 28th May 2018
Workshop Name : Friendship Motor Company

Survey Conducted At : Blk 125 Bukit Merah Lane 1

#01-168

Singapore 150125

PARTICULARS OF VEHICLE

Registration No : JSP 6997
Make/Model : Yamaha YZF25
Type Of Body : Motorcycle

 Mileage
 : 050533km

 Engine No
 : HIDDEN

 Chassis No
 : PMYRG150H0012201

Year Of Manu./Regn. : 2017

Passenger Cap. : 1 Passenger

Colour

: Blue

Others

: -

CONDITION OF TYRES

Front Tyre

: 5mm 110/70-17 IRC

Rear Tyre

: 5mm 110/70-17 IRC

The above represent the estimated remaining life of the tyre treads.

PRE-ACCIDENT CONDITION (Static tests only)

Handbrake

: Serviceable

Body Work

: Serviceable

Paint Work

: Good : Good

Footbrake Steering

: Serviceable

Others : -

POINT OF IMPACT

The vehicle sustained impacts on the front, R/H and L/H portion.

GENERAL DESCRIPTION OF DAMAGES

The main body frame, handle bar, fuel tank, forks, wheel rim, exhaust muffler were dented/bent.

For details of damages please refer to schedule attached.

REMARKS:

This survey was conducted strictly without prejudice.

Vehic	e No: JSP 6997		Our Ref:		PS/018/05/18
Qty	Descriptions	Conditions	Repairer's Est.		Our Revised.
	LIST ITEMS	worned	\$ 820.00	\$	820.00
2	front fork	warped dented	185.00	6353	185.00
1	under bracket	cracked	98.00		98.00
1	R/H fairing inner garnish		98.00		98.00
1	L/H fairing inner garnish	dented	620.00		620.00
1	radiator	dented	65.00		65.00
1	radiator hose	damaged	480.00		480.00
1	front brake caliper	sliced	105.00		105.00
1	front windshield	cracked	198.00		198.00
1	front mudguard	cracked	210.00		210.00
1	headlamp fairing	broken	285.00		285.00
1	headlamp	broken	185.00		185.00
1	headlamp stay	dented	168.00		168.00
1	headlamp wire harness	damaged	68.00		68.00
1	R/H front signal lamp	cracked	68.00		68.00
1	L/H front signal lamp	cracked	68.00		68.00
1	R/H mirror	broken	68.00		68.00
1	L/H mirror	broken	85.00		85.00
1	steering cone w/bearing	necessary	128.00		128.00
1	R/H handle bar	bent	128.00		128.00
1	L/H handle bar	bent	39.00		39.00
1	R/H handle balancer	sliced	39.00		39.00
1	L/H handle balancer	scratched	68.00		68.00
1set	handle grip	necessary	72.00		72.00
1	clutch lever	sliced	72.00		72.00
1	brake lever	sliced			860.00
1	fuel tank	dented/distorted	860.00		140.00
1	R/H fuel tank side cover	missing	140.00		140.00
1	L/H fuel tank side cover	sliced	140.00		
1	front brake disc	warped	198.00		198.00
1	front wheel rim	broken	555.00		555.00
1	horn	dented	56.00		56.00
1	lower fairing	cracked	185.00		185.00
1	R/H fairing	broken	340.00		340.00
1	L/H fairing	cracked	340.00		340.00
1	R/H front foot rest	sliced	48.00		48.00
1	L/H front foot rest	sliced	48.00		48.00
1	R/H rear foot rest	sliced	48.00		48.00
1	L/H rear foot rest	sliced	48.00		48.00
1	R/H seat side cover	dented/sliced	185.00		185.00
1	L/H seat side cover	sliced	185.00		185.00
1		fractured	58.00		58.00
1	R/H front signal lamp	scratched	58.00		58.00
1	L/H front signal lamp	bent	55.00		55.00
1	brake pedal	bent	75.00		75.00
1	gear pedal	cracked	655.00		655.00
1	speedometer	torn	325.00		325.00
1	rider seat	serviceable	625.00		
1	rear wheel rim	damaged	98.00		98.00
1	brake cable	damaged	125.00		125.00
1	throttle cable	Balance c/f	\$ 9,870.00	_	\$ 9,245.00
		Dillinio W.			

Vehic	le No: JSP 6997			Our Ref:		PS/018/05/18
Qty	Descriptions	Conditions	F	Repairer's Est.		Our Revised.
	D/U angine cover	Balance b/d serviceable	\$	9,870.00 225.00	\$	9,245.00
1	R/H engine cover	damaged		168.00		168.00
1	brake pump	serviceable		185.00		-
1	rear mudguard exhaust muffler	dented/sliced		750.00		750.00
1		serviceable		95.00		_
1	exhaust protector	00111000010	-	11,293.00		10,163.00
		Less 10%		-		1,016.30
			\$ -	11,293.00	\$	9,146.70
	S/NETT ITEMS	11		300.00		200.00
1	front tyre	wall cut		25.00		22.00
1	front number plate	necessary		40.00		40.00
1	coolant	necessary		80.00		60.00
1	engine oil	necessary		60.00		00.00
	Labour Charges & Misc					
	To dismantle & replace dama	ged parts, panel beat where				750.00
	necessary.			950.00		750.00
	To putty, apply primer & spray	-paint on the affected portion.		650.00		500.00
	To align main body frame.			400.00		320.00
	Transportation charges.		\$	50.00 13,788.00	s	40.00 11,078.70

Note: The repairer has agreed to undertake the repairs at our adjusted amount of \$8,900.00 lump sum corresponding to supply of parts, labour and spray-painting charges.

Under normal circumstances, the estimated repair period would be SEVEN (7) days.

Pursuant to your instruction we have **not** authorised repairs on your behalf.

PRESTICE APPRAISER SERVICES

LOUIS S C NG CAE AMIMI (UK)

Licensed Appraiser

Dip. MTM. Automotive Engineer