

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/GRB21010701/AES3Q2**Date:** 16/02/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SMQ143C **Insured Vehicle No :** SLS5278R
 Date of Loss: 08/10/2021 Nature of Claim: TP Claim No: MFL2021D0004601

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMQ143C**
 Make & Model: HONDA FIT, 1.3 (A) Engine No: LEB1443220
 Reg. Date: 25/10/2019 (Man. Year: 2018) Chassis No: GP51335908
 Colour: Blue Odometer: 142896 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
 Front Left Side: Grenlander 6 mm Rear Left Side: Grenlander 6 mm
 Front Right Side: Grenlander 6 mm Rear Right Side: Grenlander 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,774.60	1,974.88	2,799.72	58.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	1,040.00	860.00	45.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,674.60	3,014.88	3,659.72	54.83
Approved Total (Overridden) (S\$)		2,400.00		
Nett Amount (S\$)	6,674.60	2,400.00	4,274.60	64.04
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
Nett Liability (S\$)		2,760.00		

INSPECTION

Date of Assignment: 18/10/2021
 Date Inspected: 18/10/2021 Inspected At: ADVANCE AUTO GARAGE (#03-01) (HQ)
 10 Kaki Bukit Road 2 #03-01, First East Centre,
 Singapore 417868
 Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Jan 2022)
Parts:	144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ143C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	798.90 F	*798.90 FL
2	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	1		*FRONT BUMPER SIDE HOLDER LH	Necessary	25.90 F	*25.90 FL
4	1		*FRONT BUMPER SIDE GARNISH LH	Cut	145.30 F	*145.30 FL
5	1		*FRONT LH FENDER	Repair	368.50 F	*- FL
6	1		*FRONT LH FENDER INNER SHIELD	Torn	91.50 F	*91.50 FL
7	1		*FRONT LH FENDER INNER SHIELD CLIPS	Necessary	20.00 FS	*20.00 FS
8	1		*FRONT LH FENDER HYBRID LOGO	Necessary	48.90 F	*48.90 FL
9	1		*HEADLAMP LH	Cracked	1,170.60 F	*1,170.60 FL
10	1		*FRONT LH WHEEL RIM	Not Necessary	200.00 FS	*- FS
11	1		*FRONT LH WHEEL RIM COVER	Cut	100.00 FS	*100.00 FS
12	1		*FRONT LH TYRE	Not Necessary	250.00 FS	*- FS
13	1		*FRONT LH SHOCK ABSORBER	Not Necessary	485.20 F	*- FL
14	1		*FRONT LH KNUCKLE ARM	Not Necessary	482.30 F	*- FL
15	1		*FRONT LH LOWER ARM	Not Necessary	341.60 F	*- FL
16	1		*FRONT LH WHEEL HUB C/W BEARING	Not Necessary	215.90 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,774.60	2,431.10
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	456.22
Total Parts (\$\$)	4,774.60	1,974.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	600.00	450.00
2	SPRAY PAINTING	New	600.00	450.00
3	WIRING	New	50.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	30.00
5	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
6	TO DISMANTLE FRONT UNDERCARRIAGE	New	350.00	0.00
Gross Labour Cost (\$)			1,900.00	1,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >