

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21010704/UTF3N2**Date:** 27/10/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00180692000

**Claimant Vehicle No :** GBL5202P **Insured Vehicle No :** SMP7913G

Date of Loss: 15/10/2021 Nature of Claim: TP Claim No: SNM21D205919/C02/LEEPG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **GBL5202P**

Make & Model: SUZUKI EVERY, 658cc JOIN TURBO (A) Engine No: R06A2904218

Reg. Date: 14/09/2021 (Man. Year: 2021) Chassis No: DA17V863435

Colour: White Odometer: 942 km

Engine Capacity: 658 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 145/80R12 Rear Tyre Size: 145/80R12

Front Left Side: Bridgestone 9 mm Rear Left Side: Bridgestone 9 mm

Front Right Side: Bridgestone 9 mm Rear Right Side: Bridgestone 9 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,322.00	897.00	1,425.00	61.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,790.00	1,050.00	740.00	41.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>4,112.00</b>	<b>1,947.00</b>	<b>2,165.00</b>	<b>52.65</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	287.84	136.29	151.55	52.65
<b>Nett Amount (\$\$)</b>	<b>4,399.84</b>	<b>2,083.29</b>	<b>2,316.55</b>	<b>52.65</b>

**INSPECTION**

Date of Assignment: 18/10/2021

Date Inspected: 19/10/2021 Inspected At: Stytech Auto Pte Ltd (HQ)  
2 Kaki Bukit Ave 2 #02-30, Kaki Bukit Autohub  
Singapore 417921

Estimated Period of Repair: 3.0 days

**Adjuster:** MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 26 Oct 2021)	
<b>Parts:</b>	N/A	SUZUKI EVERY 658cc JOIN TURBO (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBL5202P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Repair	912.00 F	*- FL
2	1		*REAR BOOT EMBLEM	Not Necessary	25.00 F	*- FL
3	1		*REAR BOOT EVERY STICKER	Necessary	22.00 F	*22.00 FL
4	1		*REAR BOOT 350KG STICKER	Necessary	18.00 F	*18.00 FL
5	1		*REAR BUMPER	Dented/Bent	532.00 F	*532.00 FL
6	1		*SET REAR BUMPER CLIPS	Necessary	92.00 F	*48.00 FL
7	1		*TAILLAMP (LEFT)	Serviceable	92.00 F	*- FL
8	1		*REAR END PANEL	Repair	209.00 F	*- FL
9	1		*REAR BOOT 70KM/H STICKER	Necessary	10.00 FS	*10.00 FS
10	1		*REAR LICENCE PLATE	Scratched	40.00 FS	*40.00 FS
11	1		*SET REAR CAMERA	Shorted	120.00 FS	*120.00 FS
12	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
13	1		*REAR BOOT WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,322.00</b>	<b>990.00</b>
<b>- List Item Discount on L Items 0.00/15.00% (\$\$)</b>	0.00	93.00
<b>Total Parts (\$\$)</b>	<b>2,322.00</b>	<b>897.00</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TRANSFER REAR WINDSCREEN	New	120.00	0.00
2	TRANSFER BOOT	New	150.00	0.00
3	ANTI RUST PROOF	New	60.00	0.00
4	CHECK WIRING	New	60.00	20.00
5	PANEL BEATING	New	600.00	450.00
6	PAINT WORK	New	800.00	580.00
<b>Gross Labour Cost (\$)</b>			<b>1,790.00</b>	<b>1,050.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >