

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD	Ref:	CS/ASM21010708/Kty3e2	
	8 SHENTON WAY AXA TOWERSING		Date:	03/11/2021	
	ATTN: CHEN XIN Y	OU/	Code	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 1117R	Veh. Inspected	SGD 1324E	
	Policy No.	VFX/P2419138	Coverage (\$)	0.00	
	Claim No.	S1M03K5F	Excess (\$)	0.00	
	Assign From	CHEN XIN YOU	Assign Date	18/10/2021	
2.	2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA CAMRY (A)	c.c	2494	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	MR053AK5004010159	Colour	METALLIC SILVER	
	Odometer	163585 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	215/55 R17	MICHELIN	8 mm	
	L/H Front Tyre	215/55 R17	MICHELIN	8 mm	
	R/H Rear Tyre	215/55 R17	MICHELIN	8 mm	
	L/H Rear Tyre	215/55 R17	MICHELIN	8 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	16/10/2021	Inspection Date	19/10/2021	
	Survey held at	READY AUTO CARE PL			
		BLK 10 #03-06, AMK AUTOPOINT, ANG MO KIO AVE 5, INDUSTRIAL PARK 2A, SINGAPORE 568047			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:	4 Wor	king Days	