

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21010709/AES3Q2**Date:** 28/06/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SKT9765G	Insured Vehicle No :	SML928G
Date of Loss:	14/10/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0004557

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT9765G	Engine No:	10609049N55B30A
Make & Model:	BMW 740Li, 3.0 SR LED (A)	Chassis No:	WBAYE42040D447140
Reg. Date:	26/06/2015 (Man. Year: 2014)	Odometer:	81925 km
Colour:	Blue		
Engine Capacity:	2979 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/50 R18	Rear Tyre Size:	245/50 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,943.00	6,465.10	13,477.90	67.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,250.00	1,880.00	1,370.00	42.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,193.00	8,345.10	14,847.90	64.02
Approved Total (Overridden) (S\$)		6,600.00		
(S\$)	23,193.00	6,600.00	16,593.00	71.54
+ GST 7.00/7.00% (S\$)	1,623.51	462.00	1,161.51	71.54
Nett Amount (S\$)	24,816.51	7,062.00	17,754.51	71.54
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,469.45		
Global Sum Settlement (S\$)		7,300.00		

INSPECTION

Date of Assignment:	18/10/2021	Twincar Automotive Pte Ltd - Kaki Bukit (HQ)
Date Inspected:	19/10/2021 Inspected At:	2 KAKI BUKIT AVENUE 2, #01-17 KAKI BUKIT AUTOHUB
Estimated Period of Repair:	4.0 days	Singapore 417921

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Apr 2022)
Parts:	143	BMW 740LI 3.0 SR LED (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT9765G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,780.00 F	*1,780.00 FL
2	1		*REAR BUMPER SIDE RETAINER L/R	N/S Cracked	398.00 F	*199.00 FL
3	1		*REAR RH CONTROL ARM	Not Necessary	170.00 F	*- FL
4	1		*REAR LH DOOR (ALUMINIUM)	Dented	3,100.00 F	*2,795.00 FL
5	1		*REAR LH DOOR WEATHER STRIP	Necessary	405.00 F	*405.00 FL
6	1		*REAR LH FENDER	Repair	4,700.00 F	*- FL
7	1		*REAR LH FENDER INNER SHIELD	Not Necessary	180.00 F	*- FL
8	1		*REAR LH KNUCKLE ARM	Not Necessary	1,400.00 F	*- FL
9	1		*REAR LH KNUCKLE ARM BEARING	Damaged	230.00 F	*230.00 FL
10	1		*REAR LH LOWER ARM	Bent	630.00 F	*630.00 FL
11	1		*REAR LH SHOCK ABSORBER	Not Necessary	3,300.00 F	*- FL
12	1		*REAR LH SPORT RIM	Cut	2,100.00 FS	*1,000.00 FS
13	1		*REAR LH UPPER ARM	Not Necessary	290.00 F	*- FL
14	1		*ROCKER GARNISH LH	Not Necessary	490.00 F	*- FL
15	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
16	1		*REAR LH 245/50 R18 TYRE	Not Necessary	600.00 FS	*- FS
17	1		*SET REAR LH FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FS	*- FS
18	1		*SET ROCKER GARNISH LH CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,943.00	7,069.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	603.90
Total Parts (\$\$)	19,943.00	6,465.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RESET SYSTEM AFTER REPAIR WORKS	New	400.00	150.00
2	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	80.00	80.00
3	TO REMOVE ,CHARGE REAR SUSPENSION PARTS ,AXLE CARRIAGE ,ABSORBER ,LOWER ARM ,TOP ARM ,TRAILING ARM ,KNUCKLE ARM ,WHEEL BEARING ,BEARING HUB AND ETC	New	350.00	180.00
4	TO ROAD TEST DRIVING ,CHECK AND RESETTING WHEEL ALIGNMENT SYSTEM	New	120.00	80.00
5	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	120.00	0.00
6	TO TRANSFER DOOR GLASS ,REGULATOR GEAR ,MOTOR ,TRAILING ,CHANNEL ,TRIM BOARD ,MECHANISM LOCK AND HANDLE	New	80.00	80.00
7	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	750.00
8	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RECONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	500.00
9	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	60.00
Gross Labour Cost (\$)			3,250.00	1,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >