

ASS. REC. BY: Tan JihREF: CC4/ A162101071/T1eq3-

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FW672T Yr Regn: - 1

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha RX-2.cColour: Red A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD A/Rim orTyre Size: F: 80/80 R18R: u

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. _____ D.O.I. 19/10/21 24pmSurvey held at AS Plooon

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Total loss, chassis frame affected.

Date/Time, File Pass to?

☐ : Prel. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Rep. Format: _____

Lump Sum / L.B.A. (%) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

____ S + RS ____ SI

Photos

Others

TOTAL



潘發展私人有限公司
A. S. PHOON PTE LTD
'cos no one else

Head Off : 399, Changi Road S'pore 419846. Tel: (65) 6747 0770 Fax: (65) 6841 1263
Ubi : Blk 3007 #01-432/436 Ubi Road 1, S'pore 408701. Tel: (65) 6744 0770 Fax: (65) 6742 0250
Toh Guan : Blk 36 Toh Guan Road East #01-35 S'pore 608580 Tel: (65) 6515 0770 Fax: (65) 6515 0779
Website : www.asphoon.com Email: Enquiry@asphoon.com Co Reg No: 197701213H

FW672T YAMAHA RXZ135 REPAIR LIST

ITEM	DESCRIPTION	AMOUNT SGD
1	FRONT FENDER	\$65.00 <i>mis</i>
2	FRONT WHEEL	\$240.00 <i>? plus</i>
3	FRONT FORK LH & RH @\$240	\$480.00 <i>bt</i>
4	STEM STEERING	\$175.00 <i>ht</i>
5	CONE BEARING SET	\$60.00 <i>wt</i>
6	HEADLAMP ASSY	\$110.00 <i>aa</i>
7	STAY . HEADLAMP	\$60.00 <i>bt</i>
8	CHASSIS FRAME	--- <i>5t</i>
9	TRANSPORTATION TP TO REPORTING CENTRE TO WORKSHOP @\$60	\$120.00 ✓
TOTAL		

CHASSIS FRAME DAMAGED
LTA NOT ALLOW TO REPLACE CHASSIS FRAME
SO , WE RECOMMENDED TO TOTAL LOSS.

MARKET VALUE
\$9,000.00

prepared by,

GER ONG KEE
A.S.PHOON PTE LTD (UB BRANCH)
BLK 3007 UBI ROAD 1 #01-432/436
SINGAPORE 408701
T : 6744 0770
E : kee@asphoon.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749
wt 12/10/21 @ 4pm
c/s Keesy after repair
tanpin@lkkauto.com
5 days