

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21010720/BNF3E2

Date: 03/08/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	80417216QMY		
Claimant Vehicle No :	SLF5402S	Insured Vehicle No :	SGD2122P		
Date of Loss:	16/10/2021	Nature of Claim:	TP	Claim No:	638459

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF5402S	Engine No:	1NZR410675
Make & Model:	TOYOTA COROLLA AXIO, 1.5 HYBRID (A)	Chassis No:	NKE1657135035
Reg. Date:	30/08/2016 (Man. Year: 2016)	Odometer:	112744 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,305.79	2,935.70	6,370.09	68.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,600.00	1,280.00	1,320.00	50.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,905.79	4,215.70	7,690.09	64.59
Approved Total (Overridden) (S\$)		3,300.00		
(S\$)	11,905.79	3,300.00	8,605.79	72.28
+ GST 7.00/7.00% (S\$)	833.41	231.00	602.41	72.28
Nett Amount (S\$)	12,739.20	3,531.00	9,208.20	72.28

INSPECTION

Date of Assignment:	19/10/2021	
Date Inspected:	19/10/2021 Inspected At:	Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: Lim Teow Guan

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Oct 2021)
Parts:	143	TOYOTA COROLLA AXIO 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF5402S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	1,333.65 FL	*570.00 FL
2	1		*FRONT BUMPER RH SIDE RETAINER	Necessary	95.50 FL	*45.00 FL
3	1		*FRONT BUMPER LH SIDE RETAINER	Necessary	95.50 FL	*45.00 FL
4	1		*LH HEADLAMP ASSY	Broken	1,021.80 FL	*825.00 FL
5	1		*FRONT LH FENDER	Dented	892.30 FL	*595.20 FL
6	1		*FRONT LH FENDER HYBRID EMBLEM	Necessary	78.40 FL	*78.40 FL
7	1		*FRONT LH FENDER SPLASH SHIELD	Torn	381.80 FL	*162.00 FL
8	1		*FRONT LH SHOCK ABSORBER	Not Damaged	721.40 FL	*- FL
9	1		*FRONT LH WHEEL BEARING	Not Damaged	122.30 FL	*- FL
10	1		*FRONT LH LOWER ARM	Not Damaged	602.10 FL	*- FL
11	1		*FRONT LH LOWER ARM BALL JOINT	Not Damaged	215.80 FL	*- FL
12	1		*FRONT LH KNUCKLE ARM	Not Damaged	597.80 FL	*- FL
13	1		*FRONT LH TIE ROD END	Not Damaged	156.30 FL	*- FL
14	1		*STEERING RACK AND PINION	Not Damaged	1,645.30 FL	*- FL
15	1		*FRONT LH SIDE MIRROR ASSY	Not Damaged	1,014.60 FL	*- FL
16	1		*FRONT LH DOOR	Dented	1,379.50 FL	*1,100.00 FL
17	1		*FRONT LH DOOR FRAME BLACK TAPE	Necessary	78.00 FL	*78.00 FL
18	1		*FRONT LH DOOR FRAME BLACK TAPE (VERTICAL)	Necessary	69.00 FL	*69.00 FL
19	1		*FRONT LH SPORT RIM (LOCAL REPAIR)	Cut	850.00 FS	*200.00 FS
20	1		*FRONT LH TYRE	Not Damaged	320.00 FS	*- FS
21	1		*SET FRONT BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
22	1		*SET FRONT LH FENDER SPLASH SHIELD CLIPS	Necessary	60.00 FS	*30.00 FS
23	1		*SET FRONT LH DOOR INNER TRIM BOARD CLIPS	Not Necessary	60.00 FS	*- FS
24	1		*BRAKE FLUID	Not Necessary	70.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,931.05	3,827.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,625.26	891.90
Total Parts (\$\$)	9,305.79	2,935.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS.TO PANEL BEATING,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,000.00	600.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,000.00	600.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	70.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	50.00	0.00
5	REMOVE AND REPLACE FRONT LH UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	220.00	0.00
6	CONDUCT AND ADJUST WHEEL ALIGNMENT SYSTEM	New	100.00	0.00
7	REMOVE AND REINSTALL FRONT LH DOOR INNER COMPONENTS TO NEW DOOR	New	100.00	80.00
8	REFOCUS AND ADJUST HEADLAMP ASSY	New	60.00	0.00
Gross Labour Cost (\$\$)			2,600.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >