

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Douglas Ong Chu Chong

Date: 20 Oct 2021

Preliminary Advice

Insured Vehicle No : SGD2122P
TP Vehicle No : SLF5402S
Make : TOYOTA COROLLA AXIO
Date of Inspection : 19/10/2021
Inspection At : BIFROST AUTO PTE LTD (KAKI BUKIT)
8 KAKI BUKIT AVE 4, #01-49, PREMIER @ KAKI BUKIT
SINGAPORE 415875
Accident Date : 16/10/2021
Assignment Date : 19/10/2021
Est. Duration of Repair : 5

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,905.79
Revised Amount	:S\$	4,215.70
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,215.70
Lump Sum Repair	:S\$	3,350.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	53,000.00
COE / PARF Rebate	:S\$	28,905.00
Salvage Value	:S\$	
Margin for Repair	:S\$	24,095.00

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- () Lump Sum repair

- (x) The above survey was conducted on a 'without prejudice' basis.