



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNB 6456C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (CONSISTENT)	DENTED	1,066.10	1,066.10
1	REAR BUMPER RETAINER (CONSISTENT)	BROKEN	157.80	157.80
1	WHEEL COWLING (CONSISTENT)	BROKEN	110.00	110.00
	LESS 25% DISCOUNT		-	-333.48
			1,333.90	1,000.42
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	SET WHEEL COWLING CLIP (SN) (CONSISTENT)	NECESSARY	30.00	30.00
			60.00	60.00
LABOUR				
	LABOUR CHARGE FOR REMOVE, RENEW AND REFIT REAR BUMPER AND PANEL BEAT THE ACCIDENT AFFECTED AREAS.		700.00	600.00
	SPRAY PAINTING ON REAR BUMPER AND ACCIDENT AFFECTED AREAS ACCIDENT AFFECTED PARTS.		600.00	400.00
			1,300.00	1,000.00
GRAND TOTAL			2,693.90	2,060.42
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,650.00

Report Ref No. CS/ASM21010722/Bqy3e2

LIM TEOW GUAN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.