

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21010723/T1TF3Q2
Date: 10/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100478997
Claimant Vehicle No :	SKZ4624G	Insured Vehicle No :	SLF1407E
Date of Loss:	14/10/2021	Nature of Claim:	TP
		Claim No:	4727939305SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ4624G	Engine No:	1ZRX557803
Make & Model:	TOYOTA ALLION, 1.5 (A)	Chassis No:	MR053REH104547146
Reg. Date:	26/01/2016 (Man. Year: 2015)	Odometer:	175289 km
Colour:	Black		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

11/10/21, 4:40 PM

Adjuster Report

Date of Assignment: 19/10/2021

Date Inspected: 19/10/2021

Estimated Period of Repair: 12.0 days

Inspected At:

Jementah Motor Works (HQ)
14 Defu Lane 10, #01-406
Singapore 539195

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE:\$51,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
4	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
5	1		*FRT BUMPER SPONGE	Necessary	0.00 F	*- F
6	1		*FRT BUMPER GRILLE	Deformed	0.00 F	*- F
7	1		*FRT RH BUMPER FOG LAMP COVER	Cracked	0.00 F	*- F
8	1		*FRT RH BUMPER FOG LAMP	Cracked	0.00 F	*- F
9	1		*FRT GRILLE	Distorted	0.00 F	*- F
10	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
11	1		*FRT GRILLE CHROME MOULDING	Cut	0.00 F	*- F
12	1		*FRT SUPPORT PANEL	Bent	0.00 F	*- F
13	1		*FRT BRACE PANEL	Bent	0.00 F	*- F
14	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
15	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
16	1		*BONNET	Bent	0.00 F	*- F
17	1		*BONNET LOCK	*Check	0.00 F	*- F
18	2		*BONNET HINGE	Bent	0.00 F	*- F
19	1		*AIR CON CONDENSER	Bent	0.00 F	*- F
20	1		*RADIATOR	Cracked	0.00 F	*- F
21	1		*WIPER WASHER TANK	Deformed	0.00 F	*- F
22	1		*WIPER WASHER TANK MOTOR	Distorted	0.00 F	*- F
23	1		*FRT LH FENDER	Repair	0.00 F	*- F
24	1		*FRT RH FENDER	Bent	0.00 F	*- F
25	1		*FRT RH FENDER INNER PANEL	*Check	0.00 F	*- F
26	1		*FRT RH FENDER INNER SHIELD	Deformed	0.00 F	*- F
27	1		*FRT RH WHEEL RIM	Deformed	0.00 F	*- F
28	1		*FRT RH TYRE	*Check	0.00 F	*- F
29	1		*REAR BUMPER	Deformed	0.00 F	*- F
30	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
31	1		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
32	1		*REAR BUMPER REFLECTOR	Cracked	0.00 F	*- F
33	1		*REAR RH FENDER	Repair	0.00 F	*- F
34	1		*REAR RH WHEEL RIM	Dented	0.00 F	*- F
35	1		*REAR RH TYRE	*Check	0.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*FRT RH DOOR	Repair	0.00 F	*- F
37	1		*FRT RH QUARTER GARNISH	Deformed	0.00 F	*- F
38	1		*REAR RH DOOR	Repair	0.00 F	*- F
39	1		*FRT LH DOOR	Repair	0.00 F	*- F
40	1		*FRT RH SHOCK ABSORBER	Bent	0.00 F	*- F
41	1		*FRT KNUCKLE ARM RH	Bent	0.00 F	*- F
42	1		*FRT KNUCKLE ARM BEARING	Necessary	0.00 F	*- F
43	1		*FRT RH LOWER ARM	Bent	0.00 F	*- F
44	1		*FRT RH TIE ROD	*Check	0.00 F	*- F
45	1		*STEERING RACK & PINION	*Check	0.00 F	*- F
46	1		*FRT RH DRIVE SHAFT	*Check	0.00 F	*- F
47	1		*REAR RH WHEEL HUB BEARING	*Check	0.00 F	*- F
48	1		*REAR RH SHOCK ABSORBER	*Check	0.00 F	*- F
49	1		*REAR AXLE ASSY	*Check	0.00 F	*- F
F=Franchise part.						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >