



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 6593J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HEADLAMP RH	CRACKED	603.20	603.20
1	HEADLAMP LOWER BEAM	SERVICEABLE	36.50	-
1	FRONT BUMPER	TO REPAIR SEE LABOUR	731.20	-
1	FRONT BUMPER SIDE RETAINER RH	SERVICEABLE	24.30	-
12	FRONT BUMPER CLIPS	NOT NECESSARY	42.00	-
1	FRONT FENDER RH	BENT	486.20	486.20
3	FRONT FENDER TOP GARNISH CLIPS	NOT NECESSARY	10.50	-
1	FRONT FENDER COWLING RH	SERVICEABLE	80.20	-
8	FRONT FENDER COWLING CLIPS	NOT NECESSARY	28.00	-
1	WIPER GARNISH SIDE COVER RH	SERVICEABLE	195.20	-
1	ROOF MOULDING RH	SERVICEABLE	197.20	-
1	FRONT DOOR RH	BENT	860.20	860.20
1	FRONT DOOR OUTER HANDLE COVER RH (NPA)	SERVICEABLE	-	-
1	FRONT DOOR WINDOW MOULDING	SERVICEABLE	82.90	-
1	FRONT DOOR HINGE TOP	TO REPAIR SEE LABOUR	34.10	-
1	FRONT DOOR OUTER HANDLE RH	DENTED	153.20	153.20
1	FRONT DOOR LOCK	TO REPAIR SEE LABOUR	316.40	-
1	FRONT DOOR RUBBER (AT DOOR) RH	SERVICEABLE	152.40	-
1	FRONT DOOR TAPE SET RH	NECESSARY	48.20	48.20
1	SIDE MIRROR ASSY RH	CRACKED	474.10	474.10
1	REAR DOOR OUTER HANDLE RH	DENTED	143.20	143.20
1	REAR DOOR OUTER HANDLE COVER RH (NPA)	SERVICEABLE	-	-
1	REAR DOOR WINDOW MOULDING RH	SERVICEABLE	80.40	-
1	FRONT SIGNAL LAMP RH	SERVICEABLE	18.20	-
	LESS 20% DISCOUNT		-959.56	-553.66
			3,838.24	2,214.64

Report Ref No. CS/SMR21010724/Kuf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		40.00	20.00
	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR / FACILITATE REPAIR.		120.00	80.00
	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.		60.00	60.00
	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD. TO KNOCK & REPAIR FRONT BONNET, REAR DOOR RH, REAR FENDER RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME. INCLUSIVE OF THE REPAIR OF FRONT BUMPER, FRONT DOOR HINGE TOP AND FRONT DOOR LOCK.		700.00	500.00
	TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER RH, FRONT DOOR RH, REAR DOOR RH, REAR FENDER RH, SIDE MIRROR COVER RH.		1,300.00	1,000.00
			2,300.00	1,660.00
GRAND TOTAL			6,138.24	3,874.64
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,100.00

Report Ref No. CS/SMR21010724/Kuf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.