

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIG21010726/EVF3E2

**Date:** 08/11/2021

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900141126
<b>Claimant Vehicle No :</b>	SBS5128J	<b>Insured Vehicle No :</b>	SMN9838M
Date of Loss:	13/10/2021	Nature of Claim:	TP
		Claim No:	8741816271SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SBS5128J</b>	Engine No:	6422304
Make & Model:	SCANIA KUB4X2 9.3L A/T ABS TURBO, 9.3 D (A)	Chassis No:	YS2K4X20001866360
Reg. Date:	09/02/2010 (Man. Year: 2009)	Odometer:	1024996 km
Colour:	Multi-colour		
Engine Capacity:	9290 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5 (D)
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4/4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4/4 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	933.00	933.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	400.00	400.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,333.00</b>	<b>1,333.00</b>	<b>0.00</b>	<b>0.00</b>
<b>+ GST 7.00/7.00% (S\$)</b>	93.31	93.31	0.00	0.00
<b>Nett Amount (S\$)</b>	<b>1,426.31</b>	<b>1,426.31</b>	<b>0.00</b>	<b>0.00</b>

### INSPECTION

Date of Assignment:	19/10/2021	Sbs Transit Pte Ltd (ulu Pandan) (HQ)
Date Inspected:	19/10/2021 Inspected At:	Ulu Pandan WS, 1 Business Park Drive, Singapore 608506.
Estimated Period of Repair:	2.0 days	Singapore 608506

**Adjuster:** CHEN TSUE YEE

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR FRAME	Dented	321.00 F	*321.00 F
2	1		*RADIATOR PANEL GRILL	Dented	612.00 F	*612.00 F
F=Franchise part.						
Total Parts (S\$)					933.00	933.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR - REPLACE DAMAGED PARTS }	New	400.00	400.00
2	SPRAY PAINT & PUTTY - PAINT & PUTTY DAMAGED PARTS }	New	0.00	0.00
3	STICKER LIVERY - PURPLE }	New	0.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>400.00</b>	<b>400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >