

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21010727/KTF3N2**Date:** 28/10/2021REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A291417717AT2

Claimant Vehicle No : SGR5314J**Insured Vehicle No :** SLW8788U

Date of Loss: 17/10/2021

Nature of Claim: TP

Claim No: 638458

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SGR5314J**

Make & Model: TOYOTA WISH, 1.8 (A)

Engine No: 1ZZ2820119

Reg. Date: 09/02/2007 (Man. Year: 2016)

Chassis No: ZNE100350680

Colour: Metallic Grey

Odometer: 229343 km

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15

Rear Tyre Size: 195/65R15

Front Left Side: RAPID 6 mm

Rear Left Side: Kumho 5 mm

Front Right Side: RAPID 6 mm

Rear Right Side: Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,447.62	3,469.05	2,978.57	46.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,740.00	1,480.00	260.00	14.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,187.62	4,949.05	3,238.57	39.55
Approved Total (Overridden) (\$\$)		2,800.00		
(\$\$)	8,187.62	2,800.00	5,387.62	65.80
+ GST 7.00/7.00% (\$\$)	573.13	196.00	377.13	65.80
Nett Amount (\$\$)	8,760.75	2,996.00	5,764.75	65.80

INSPECTION

Date of Assignment: 19/10/2021

Date Inspected: 19/10/2021 Inspected At:

Chew Goon Motor (AMK)
Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 &
17, AMK Autopoint
Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Oct 2021)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGR5314J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	731.00 FL	*731.00 FL
2	2		*BONNET HINGES	Bent	97.60 FL	*97.60 FL
3	1		*BONNET RUBBER SEAL	Serviceable	39.20 FL	*- FL
4	8		*BONNET INSULATOR CLIPS	Not Necessary	44.00 FL	*- FL
5	1		*BONNET MOULDING	Dented	197.00 FL	*197.00 FL
6	1		*WINDSCREEN GARNISH RH	Serviceable	52.00 FL	*- FL
7	1		*HEADLAMP LH	Broken	865.00 FL	*865.00 FL
8	1		*HEADLAMP PANEL LH	Bent	822.00 FL	*822.00 FL
9	1		*FRONT BUMPER	Cracked	486.00 FL	*486.00 FL
10	10		*FRONT BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL
11	1		*FRONT BUMPER BRACKETS LH	Distorted	45.60 FL	*45.60 FL
12	1		*FRONT BUMPER SPONGE	Cracked	105.00 FL	*105.00 FL
13	1		*FRONT BUMPER REINFORCEMENT	Bent	302.00 FL	*302.00 FL
14	1		*FRONT BUMPER CORNER RETAINER LH	Cracked	54.70 FL	*54.70 FL
15	1		*FRONT BUMPER FOG LAMP COVER LH	Serviceable	105.40 FL	*- FL
16	1		*FRONT FENDER LH	Bent	723.40 FL	*723.40 FL
17	1		*FRONT FENDER SHIELD	Missing	120.10 FL	*120.10 FL
18	10		*FRONT FENDER SHIELD CLIPS	Necessary	38.00 FL	*38.00 FL
19	1		*MAIN FUSE BOX LH	Serviceable	865.00 FL	*- FL
20	1		*FRONT SHOCK ABSORBER	Serviceable	413.80 FL	*- FL
21	1		*AIR CLEANER BOX	Serviceable	435.00 FL	*- FL
22	1		*AIR CLEANER BOX LOWER HOSE	Serviceable	261.80 FL	*- FL
23	1		*FRONT KNUCKLE ARM (NPA)	Not Necessary	0.00 FL	*- FL
24	1		*FRONT KNUCKLE ARM	Serviceable	555.00 FL	*- FL
25	1		*FRONT KNUCKLE ARM BEARING	Not Necessary	130.90 FL	*- FL
26	1		*FRONT LOWER ARM BALL JOINT	Not Necessary	196.20 FL	*- FL
27	1		*FRONT WHEEL HUB	Serviceable	79.80 FL	*- FL
28	1		*BATTERY	Serviceable	145.00 FS	*- FS
29	1		*FRONT WHEEL RIM LH	Serviceable	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,398.50	4,625.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,950.88	1,156.35
Total Parts (\$\$)	6,447.62	3,469.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CONDUCT ELECTRICAL CHECK,FOCUS HEADLAMP	New	30.00	20.00
2	TO APPLY RUST PROOFING/RESEAL TUFF COATING TREATMENT TO RESPRAY/REPLACED/REPAIR PANEL	New	50.00	50.00
3	TO PROVIDE TRANSPORTATION (TOWING)	New	60.00	50.00
4	TO DISMANTLE/HI PRESSURE PRESS/REPLACE WHEEL BEARING	New	70.00	0.00
5	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST	New	80.00	60.00
6	LABOUR CHARGE-PANEL BEATING,REPAIRING OF FRONT CHASSIS MEMBER,FENDER INNER PANEL,FRONT LH DOOR ETC.CNT,WELD HEADLAMP PANEL AND PARTS REPLACEMENT	New	600.00	550.00
7	TO RESPRAY AFFECTED AREAS	New	850.00	750.00
Gross Labour Cost (\$\$)			1,740.00	1,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >