

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III21010728/KPA3Q2**Date:** 26/07/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D18MPC0000708\_03

**Claimant Vehicle No :** SCG5007B **Insured Vehicle No :** SJX8693C

Date of Loss: 13/10/2021 Nature of Claim: TP Claim No: MPC2021D0004442

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCG5007B**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4955084

Reg. Date: 15/01/2010 (Man. Year: 2009) Chassis No: MR053ZEE106162372

Colour: Metallic Black Odometer: 206456 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Falken 5 mm Rear Left Side: Yokohama 3 mm

Front Right Side: Falken 5 mm Rear Right Side: Yokohama 3 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,769.48	513.67	1,255.81	70.97
Miscellaneous Items	211.00	11.00	200.00	94.79
Labour	1,050.00	400.00	650.00	61.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,030.48</b>	<b>924.67</b>	<b>2,105.81</b>	<b>69.49</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>700.00</b>		
<b>(S\$)</b>	3,030.48	700.00	2,330.48	76.90
<b>+ GST 7.00/7.00% (S\$)</b>	212.13	49.00	163.13	76.90
<b>Nett Amount (S\$)</b>	<b>3,242.61</b>	<b>749.00</b>	<b>2,493.61</b>	<b>76.90</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

INSPECTION

Date of Assignment: 19/10/2021 Present Location: City Auto Pte Ltd (HQ)

Date Inspected: 22/10/2021 Inspected At: City Auto Pte Ltd (HQ)

Estimated Period of Repair: 3.0 days 160 Sin Ming Drive #05-01,, Sin Ming AutoCity, Singapore 575722

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Jul 2022)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCG5007B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Rear bumper	Bent	612.00 FL	*612.00 FL
2	1		*Rear bumper reinforcement	*Check	142.60 FL	*- FL
3	1		*Rear bumper retainer	Distorted	72.90 FL	*72.90 FL
4	1		*Tail lamp RH	*Check	525.70 FL	*- FL
5	3		*Rear boot emblem	Not Necessary	132.51 FL	*- FL
6	1		*Rear boot lamp	Serviceable	873.60 FL	*- FL
					Sub Total (S\$)	2,359.31 684.90
					- List Item Discount on L Items 25.00/25.00% (S\$)	589.83 171.23
					Total Parts (S\$)	1,769.48 513.67

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	Reverse sensor Serviceable	200.00	0.00
2	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			211.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	- To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	New	450.00	200.00
2	- Spary painting on affected and replace parts	New	600.00	200.00
Gross Labour Cost (\$\$)			1,050.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >