

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI21010729/VVF3N2**Date:** 01/11/2021**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MV000656
Claimant Vehicle No :	SH6080L	Insured Vehicle No :	GBB7601K
Date of Loss:	17/10/2021	Nature of Claim:	TP
		Claim No:	M2104836

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH6080L	Engine No:	G4LEKU421524
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVLU192928
Reg. Date:	29/04/2021 (Man. Year: 2019)	Odometer:	70636 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	939.76	938.16	1.60	0.17
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	820.00	630.00	190.00	23.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,770.76	1,579.16	191.60	10.82
+ GST 7.00/7.00% (S\$)	123.95	110.54	13.41	10.82
Nett Amount (S\$)	1,894.71	1,689.70	205.01	10.82

INSPECTION

Date of Assignment:	19/10/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	18/10/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang)
			59 Loyang Drive
			Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: Thevan Thomas Karthikesavan**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Oct 2021)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH6080L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Deformed	459.40 FL	-	*459.40 FL
2	1		*REAR BUMPER SIDE BRACKET LH	Necessary	138.10 FL	-	*138.10 FL
3	1		*REAR BUMPER REFLECTOR LH	Scratched	41.45 FL	-	*41.45 FL
4	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*20.00 FL
5	1		*REAR BUMPER MAT	Necessary	50.00 F	-	*50.00 FS
6	1		*REAR BUMPER CENTRE MOULDING	Scratched	451.25 FL	-	*451.25 FL
					Sub Total (\$\$)	1,162.20	1,160.20
					- List Item Discount on L Items 20.00/20.00% (\$\$)	222.44	222.04
					Total Parts (\$\$)	939.76	938.16

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING	New	300.00	250.00
3	R/I REVERSE SENSORS	New	120.00	30.00
Gross Labour Cost (\$\$)			820.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >