

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE I	PTE LTD		Ref:	CS3/ASM21010734/Eqy3e2	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11		Date:	25/10/2021	
	ATTN: ANG YVONI	NE		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHC 3663G	Veh. Inspected	t	FW 9236K	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S1M03K0M	Excess (\$)		0.00	
	Assign From	ANG YVONNE	Assign Date		19/10/2021	
2. Vehicle Particulars & Condition						
	Make & Model	YAMAHA RXZ	c.c		133	
	Engine No.	HIDDEN	Year of Reg.		2003	
	Chassis No.	PMY5PV10000003418	Colour		WHITE	
	Odometer	1963 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	2.75-18	PIRELLI		3 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	3.00-18	PIRELLI		3 mm	
	L/H Rear Tyre				mm	
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
5.	General Information					
	Accident Date	14/10/2021	Inspect Date /	Time	19/10/2021 (02:50 PM)	
	Survey held at	Blk 1005 Bukit Merah Lane 2 #01	-18 Singapore159	761		
	Repairer	Repairer FRIENDSHIP MOTOR CO				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					

Report Ref No. CS3/ASM21010734/Eqy3e2

Inspected By

CHEN TSUE YEE

K.K.LAU CPT(RET)

Automotive Assessor

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser