

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNA 5468E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	TORN	1,315.00	1,315.00
1	FRONT BUMPER SPONGE	TORN	268.00	268.00
1	FRONT BUMPER BEAM	TO REPAIR SEE LABOUR	466.00	-
2	FRONT BUMPER SIDE RETAINERS \$@98.00	NECESSARY	196.00	196.00
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT GRILLE	CRACKED	850.00	850.00
1	FRONT GRILLE RADAR SENSOR	SHORTED	900.00	900.00
1	FRONT GRILLE OUTER RADAR SENSOR COVER	CRACKED	150.00	150.00
1	SET FRONT GRILLE CLIPS	NECESSARY	45.00	45.00
1	FRONT SUPPORT PANEL TOP GARNISH	CRACKED	425.00	425.00
1	SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	NECESSARY	30.00	30.00
1	BONNET	TO REPAIR SEE LABOUR	1,480.00	-
1	BONNET LOGO	NECESSARY	105.00	105.00
	LESS 10% DISCOUNT		-628.00	-433.40
			5,652.00	3,900.60
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REFIX FRONT PDC SENSOR.		80.00	50.00
	TO RESET & REPROGRAMME DIAGNOSIS SYSTEM.		120.00	100.00
	TO REFILL AIR CON GAS.	NOT NECESSARY	120.00	-
	TO SPARY RUST PROOFING.	NOT NECESSARY	80.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER BEAM AND BONNET.		850.00	600.00
	TO PUTTY & SPRAY PAINTING.		880.00	500.00
			2,180.00	1,270.00
	GRAND TOTAL		7,832.00	5,170.60

Report Ref No. CS/TP21010736/Uvf3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,100.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/TP21010736/Uvf3e2

CHUA KANG SENG
Licensed Appraiser