

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21010740/ATY3N2**Date:** 20/05/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00002542103	
<b>Claimant Vehicle No :</b>	SME5833A	<b>Insured Vehicle No :</b>	GBF5827T	
Date of Loss:	17/10/2021	Nature of Claim:	TP	Claim No: SNM21D205922/C02/THAMYL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SME5833A</b>		Engine No:	LEB5608509
Make & Model:	HONDA FREED HYBRID, 1.5 (A)		Chassis No:	GB71073721
Reg. Date:	05/10/2018 (Man. Year: 2018)		Odometer:	87813 km
Colour:	Blue			
Engine Capacity:	1496 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>			

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	215/45R17	Rear Tyre Size:	215/45R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,086.12	4,792.72	4,293.40	47.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	860.00	1,440.00	62.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>11,386.12</b>	<b>5,652.72</b>	<b>5,733.40</b>	<b>50.35</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,500.00</b>		
<b>(\$\$)</b>	11,386.12	4,500.00	6,886.12	60.48
<b>+ GST 7.00/7.00% (\$\$)</b>	797.03	315.00	482.03	60.48
<b>Nett Amount (\$\$)</b>	<b>12,183.15</b>	<b>4,815.00</b>	<b>7,368.15</b>	<b>60.48</b>

**INSPECTION**

Date of Assignment:	17/11/2021	
Date Inspected:	19/10/2021 Inspected At:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	3.0 days	

**Adjuster:** ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 May 2022)
Parts:	M1-MPV	HONDA FREED HYBRID 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME5833A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT AIRCON ALUMINIUM PIPE	Not Necessary	425.00 FL	*- FL
2	1		*FRONT BUMPER LOWER GRILLE (MODURO X)	Cut	298.00 FL	*298.00 FL
3	1		*FRONT BUMPER REINFORCEMENT	Dented	398.00 FL	*398.00 FL
4	1		*FRONT BUMPER RH FOGLAMP (LED)	Cracked	425.00 FL	*425.00 FL
5	1		*FRONT BUMPER SIDE RETAINER L/R	O/s Damaged	50.00 FL	*25.00 FL
6	1		*FRONT GRILLE LOGO EMBLEM	Necessary	35.00 FL	*35.00 FL
7	1		*FRONT GRILLE (MODURO X)	Cracked	901.00 FL	*901.00 FL
8	1		*FRONT HEADLAMP L/R	O/s Cracked	2,916.40 FL	*1,458.20 FL
9	1		*FRONT HEADLAMP LOWER BRACKET L/R	O/s Cracked	73.00 FL	*36.50 FL
10	1		*FRONT RH FENDER HYBRID EMBLEM	Necessary	68.80 FL	*68.80 FL
11	1		*FRONT RH FENDER INNER PANEL	Repair	533.20 FL	*- FL
12	1		*FRONT RH FENDER INNER SHIELD	Torn	120.40 FL	*120.40 FL
13	1		*FRONT SUPPORT PANEL	Not Necessary	752.60 FL	*- FL
14	1		*FRONT BUMPER (MODURO X)	Distorted	2,484.00 FS	*1,600.00 FS
15	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
16	1		*FRONT BUMPER NUMBER PLATE	Not Necessary	25.00 FS	*- FS
17	1		*FRONT BUMPER NUMBER PLATE HOLDER	Not Necessary	100.00 FS	*- FS
18	1		*FRONT BUMPER REINFORCEMENT BAR	Not Necessary	450.00 FS	*- FS
19	1		*FRONT BUMPER SIDE LED LAMP RH	Cracked	250.00 FS	*120.00 FS
20	1		*SET FRONT RH FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*30.00 FS
21	1		*RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (S\$)	10,485.40 5,545.90
					- List Item Discount on L Items 20.00/20.00% (S\$)	1,399.28 753.18
					Total Parts (S\$)	9,086.12 4,792.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,CHANGE AIR CON PARTS,VACUUMS,REFILL AIR CON GAS	New	120.00	0.00
2	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING (TO FR)	New	80.00	30.00
3	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	400.00
4	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	400.00
5	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	30.00
<b>Gross Labour Cost (\$)</b>			<b>2,300.00</b>	<b>860.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >