

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI21010742/VTF3N2**Date:** 05/11/2021REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	ML000183		
Claimant Vehicle No :	SHA1852B	Insured Vehicle No :	GBH994R		
Date of Loss:	18/10/2021	Nature of Claim:	TP	Claim No:	M2104843

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA1852B	Engine No:	2ZR2G06294
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT TAXI (A)	Chassis No:	JTDKB3FU003090344
Reg. Date:	20/12/2019 (Man. Year: 2019)	Odometer:	141108 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,626.17	972.62	653.55	40.19
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	820.00	630.00	190.00	23.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,457.17	1,613.62	843.55	34.33
+ GST 7.00/7.00% (S\$)	172.00	112.95	59.05	34.33
Nett Amount (S\$)	2,629.17	1,726.57	902.60	34.33

INSPECTION

Date of Assignment:	19/10/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	19/10/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang)
			59 Loyang Drive
			Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: Thevan Thomas Karthikesavan**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Nov 2021)

Parts: 144 TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHA1852B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Cut	458.60 FL	-	*458.60 FL
2	1		*REAR BUMPER UNDER COVER	Cut	552.60 FL	-	*552.60 FL
3	1		*REAR BUMPER REINFORCEMENT	Serviceable	318.80 FL	-	*- FL
4	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
5	1		*REAR BUMPER TOW COVER	Cut	82.70 FL	-	*82.70 FL
6	1		*REVERSE SENSORS	Cut	135.70 F	-	*135.70 FS
7	1		*REAR BUMPER UNDER FLOOR COVER	Serviceable	552.60 FL	-	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,123.00	1,251.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	496.83	278.98
Total Parts (\$\$)	1,626.17	972.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING	New	300.00	250.00
3	R/I REVERSE SENSORS	New	120.00	30.00
Gross Labour Cost (\$\$)			820.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >