

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21010749/T1TF3E2

Date: 19/11/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100484920-05
Claimant Vehicle No :	FBB5323B	Insured Vehicle No :	SFB9292H
Date of Loss:	14/10/2021	Nature of Claim:	TP
		Claim No:	4940355824SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBB5323B	Engine No:	5YP205115
Make & Model:	YAMAHA SPARK, 135cc	Chassis No:	5YP205115
Reg. Date:	04/05/2007 (Man. Year: 2006)	Odometer:	39331 km
Colour:	Black		
Engine Capacity:	135 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70/90 R17	Rear Tyre Size:	80/90 R17
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,969.50	1,790.25	5,179.25	74.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	660.00	430.00	230.00	34.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,629.50	2,220.25	5,409.25	70.90
Approved Total (Overridden) (S\$)		900.00		
Nett Amount (S\$)	7,629.50	900.00	6,729.50	88.20

INSPECTION

Date of Assignment:	19/10/2021		
Date Inspected:	20/10/2021	Inspected At:	TSL Auto Garage Synergy Building, Kaki Bukit #01-44 Singapore 417800
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET FRONT HANDLE BAR	Not Necessary	275.00 FL	*- FL
2	1		*FRONT HANDLE BAR GRIP WITH BALANCER	N/S NotNecessary / O/S Cut	45.00 FL	*22.50 FL
3	1		*FRONT HEADLAMP ASSY	Not Necessary	285.00 FL	*- FL
4	1		*FRONT HEADLAMP STAY BRACKET	Not Necessary	65.00 FL	*- FL
5	1		*FRONT HEADLAMP TOP COWLING	Not Necessary	155.00 FL	*- FL
6	1		*FRONT HEADLAMP OUTER COWLING	Not Necessary	225.00 FL	*- FL
7	1		*FRONT LEFT SIDE TOP FAIRING	Not Necessary	295.00 FL	*- FL
8	1		*FRONT RIGHT SIDE TOP FAIRING	Cut	295.00 FL	*295.00 FL
9	1		*FRONT LEFT SIDE LOWER FAIRING	Not Necessary	395.00 FL	*- FL
10	1		*FRONT RIGHT SIDE LOWER FAIRING	Cut	395.00 FL	*395.00 FL
11	1		*FRONT LEFT SIDE LAMP	Not Necessary	125.00 FL	*- FL
12	1		*FRONT RIGHT SIDE LAMP	Cracked	125.00 FL	*125.00 FL
13	1		*FRONT LEFT SIDE MIRROR	Not Necessary	65.00 FL	*- FL
14	1		*FRONT RIGHT SIDE MIRROR	Cut	65.00 FL	*65.00 FL
15	1		*FRONT FENDER	Cut	105.00 FL	*105.00 FL
16	1		*SET FRONT FORK ASSY	Shifted	1,030.00 FN	*120.00 F
17	2		*FRONT FORK STEM	Not Necessary	45.00 FL	*- FL
18	1		*FRONT BRAKE LEVER	Not Necessary	65.00 FL	*- FL
19	1		*FRONT CLUTCH LEVER	Cut	65.00 FL	*65.00 FL
20	1		*FRONT RIGHT FOOT BRAKE	Bent	55.00 FL	*55.00 FL
21	1		*FRONT RIGHT FOOT REST	Bent	55.00 FL	*55.00 FL
22	1		*FRONT LEFT GEAR SELECTOR	Not Necessary	55.00 FL	*- FL
23	1		*FRONT LEFT FOOT REST	Not Necessary	55.00 FL	*- FL
24	1		*FRONT METER ASSY	Not Necessary	295.00 FL	*- FL
25	1		*FRONT WHEEL RIM	Not Necessary	450.00 FL	*- FL
26	1		*FRONT WHEEL SHAFT	Not Necessary	95.00 FL	*- FL
27	1		*FRONT BRAKE CALIPER	Not Necessary	175.00 FL	*- FL
28	1		*FRONT BRAKE RESERVOIR	Not Necessary	65.00 FL	*- FL
29	1		*REAR LEFT SIDE FAIRING	Not Necessary	195.00 FL	*- FL
30	1		*REAR RIGHT SIDE FAIRING	Cut	195.00 FL	*195.00 FL
31	1		*REAR EXHAUST MUFFLER ASSY	Not Necessary	625.00 FL	*- FL
32	1		*REAR EXHAUST MUFFLER CHROME PROTECTOR	Dented	145.00 FL	*145.00 FL
33	1		*REAR LEFT PILLION FOOT REST	Not Necessary	55.00 FL	*- FL
34	1		*REAR RIGHT PILLION FOOT REST	Not Necessary	55.00 FL	*- FL
35	1		*REAR LEFT SIDE COVER	Not Necessary	35.00 FL	*- FL
36	1		*REAR RIGHT SIDE COVER	Not Necessary	35.00 FL	*- FL
37	1		*SIDE STAND	Not Necessary	45.00 FL	*- FL
38	1		*FRONT NO PLATE	Not Necessary	35.00 FS	*- FS
39	1		*ERP IU	Not Necessary	180.00 FS	*- FS
40	1		*ERP IU BRACKET	Not Necessary	35.00 FS	*- FS
41	2		*FRONT FORK OIL	Not Necessary	60.00 FS	*- FS
42	1		*REAR NO PLATE	Not Necessary	35.00 FS	*- FS
43	1		*REAR BOX ASSY	Cut	300.00 FS	*300.00 FS
44	1		*REAR BOX BRACKET	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	7,650.00	1,942.50
- List Item Discount on L Items 10.00/10.00% (\$\$)	577.50	152.25
- Nett Item Discount on N Items 10.00/0.00% (\$\$)	103.00	0.00
Total Parts (\$\$)	6,969.50	1,790.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	300.00	200.00
2	WIRING	New	60.00	30.00
3	SPRAY PAINTING	New	300.00	200.00
Gross Labour Cost (\$)			660.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >