

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21010750/TRA3Q2**Date:** 16/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800031124
<b>Claimant Vehicle No :</b>	SDH9588Y	<b>Insured Vehicle No :</b>	SLX6651M
Date of Loss:	15/10/2021	Nature of Claim:	TP
		Claim No:	8314522803SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SDH9588Y</b>	Engine No:	R18A1741790
Make & Model:	HONDA STREAM, 1.8 (A)	Chassis No:	RN61036962
Reg. Date:	21/09/2007 (Man. Year: 2007)	Odometer:	238098 km
Colour:	Grey		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65 R15	Rear Tyre Size:	205/65 R15
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,167.48	4,704.04	4,463.44	48.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,980.00	2,330.00	1,650.00	41.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,147.48</b>	<b>7,034.04</b>	<b>6,113.44</b>	<b>46.50</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,600.00</b>		
<b>(S\$)</b>	13,147.48	5,600.00	7,547.48	57.41
<b>+ GST 7.00/7.00% (S\$)</b>	920.32	392.00	528.32	57.41
<b>Nett Amount (S\$)</b>	<b>14,067.80</b>	<b>5,992.00</b>	<b>8,075.80</b>	<b>57.41</b>
<b>+ Car Rental (9.0 x S\$120.00/day) (S\$)</b>		1,080.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>7,074.00</b>		

INSPECTION

Date of Assignment:	19/10/2021	Abwin Service Pte Ltd -( 17 Kaki Bukit Road 4 ) (HQ)
Date Inspected:	19/10/2021 Inspected At:	No.17 Kaki Bukit Road 4, #01-60 Bartley Biz Centre Singapore 417809
Estimated Period of Repair:	7.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	991.20 FL	*991.20 FL
2	1		*TAILGATE INNER TRIM	Cracked	170.30 FL	*170.30 FL
3	1		*TAILGATE INNER TRIM HANDLE	Deformed	20.70 FL	*20.70 FL
4	1		*TAILGATE HINGE RH	Repair	52.30 FL	*- FL
5	1		*TAILGATE HINGE LH	Repair	52.30 FL	*- FL
6	1		*TAILGATE EMBLEM LOGO HONDA	Necessary	24.70 FL	*24.70 FL
7	1		*TAILGATE EMBLEM STREAM	Necessary	36.00 FL	*36.00 FL
8	1		*TAILGATE LOCK TOP	Bent	124.50 FL	*124.50 FL
9	1		*TAILGATE LOCK BOTTOM	Bent	27.00 FL	*27.00 FL
10	1		*TAILGATE WINDSCREEN MOULDING	Necessary	118.00 FL	*118.00 FL
11	1		*TAILGATE WEATHER STRIP	Cut	137.50 FL	*137.50 FL
12	1		*TAILGATE OUTER GARNISH	Not Necessary	183.50 FL	*- FL
13	1		*TAIL LAMP RH	Not Necessary	459.20 FL	*- FL
14	1		*TAIL LAMP LH	Cracked	459.20 FL	*459.20 FL
15	1		*REAR BUMPER	Deformed	704.90 FL	*704.90 FL
16	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	24.00 FL	*- FL
17	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	24.00 FL	*- FL
18	1		*REAR SMART BUZZER	Not Necessary	85.00 FL	*- FL
19	1		*REAR BUMPER TOWING COVER	Deformed	18.00 FL	*18.00 FL
20	1		*REAR END PANEL OUTER	Bent	346.80 FL	*346.80 FL
21	1		*REAR END PANEL INNER	Bent	158.10 FL	*158.10 FL
22	1		*REAR END PANEL TOP GARNISH	Deformed	140.90 FL	*140.90 FL
23	1		*FLOOR PANEL	Buckled	1,190.50 FL	*1,190.50 FL
24	1		*FLOOR PANEL TOP BOARD	Not Necessary	145.20 FL	*- FL
25	1		*REAR EXTENSION PANEL RH	Repair	562.50 FL	*- FL
26	1		*TOOLS TOP BOX	Not Necessary	129.50 FL	*- FL
27	1		*SPARE TYRE BRACKET	Not Necessary	165.90 FL	*- FL
28	1		*REAR TOOLS COMPARTMENT	Not Necessary	249.80 FL	*- FL
29	1		*TAILGATE CABLE	Not Necessary	75.00 FL	*- FL
30	1		*TAILGATE ABSORBER RH	Not Necessary	132.90 FL	*- FL
31	1		*TAILGATE ABSORBER LH	Not Necessary	132.90 FL	*- FL
32	1		*REAR AXLE (NPA)	Not Necessary	0.00 FL	*- FL
33	1		*EXHAUST	Repair	588.40 FL	*- FL
34	1		*EXHAUST ALUMINIUM HEAT SHIELD	Bent	60.50 FL	*60.50 FL
35	1		*REAR FENDER RH	Not Necessary	977.20 FL	*- FL
36	1		*REAR FENDER LH	Not Necessary	977.20 FL	*- FL
37	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
38	1		*TAILGATE SEALANT	Necessary	50.00 FS	*40.00 FS
39	1		*REVERSE CAMERA	Not Necessary	380.00 FS	*- FS
40	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*40.00 FS
41	1		*WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS
42	10		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
43	1		*REAR NUMBER PLATE	Bent	45.00 FS	*45.00 FS
44	1		*FENDER INNER BOARD RH	Cracked	245.00 FL	*245.00 FL
45	1		*FENDER INNER BOARD LH	Cracked	245.00 FL	*245.00 FL
46	1		*SPARE TYRE	Bent	380.00 FL	*380.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>11,290.60</b>	<b>5,823.80</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	2,123.12	1,119.76
<b>Total Parts (\$)</b>	<b>9,167.48</b>	<b>4,704.04</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	New	1,600.00	1,100.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	1,600.00	1,000.00
3	TO APPLY TUFF COAT ON AFFECTED AREAS	New	180.00	40.00
4	TO DISMANTLE ,REPLACE AND OR REPAIR TAILGATE COMPONENTS	New	250.00	60.00
5	TO DISMANTLE ,REPLACE AND /OR REPAIR REVERSE CAMERA & TESTING	New	150.00	50.00
6	TO DISMANTLE & REFIX INTERIOR UPHOLSTERY	New	200.00	80.00
			<b>Gross Labour Cost (\$\$)</b>	<b>2,330.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >